

PROBLEM SUMMARY

Sample Rating Trend


ISO

BUMP ON [355150]

MULTI PRESS SMP2 - SEGMENT MAKER PRESS 2 (S/N M-5963)


Hydraulic System

MOBIL DTE 26 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL	ABNORMAL	ABNORMAL			
Particles >4µm	ASTM D7647	>5000	<u> </u>	<u>^</u> 26880	<u>23445</u>			
Particles >6µm	ASTM D7647	>1300	<u>2217</u>	2982	<u>\$\text{\scale}\$ 2509</u>			
Oil Cleanliness	ISO 4406 (c)	>19/17/14	<u>^</u> 21/18/13	<u>^</u> 22/19/14	22/19/13			

Customer Id: THRFAI Sample No.: USP245269 Lab Number: 05924866 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

03 Aug 2022 Diag: Doug Bogart

ISO



Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



04 Aug 2021 Diag: Doug Bogart

150



Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



16 Jul 2020 Diag: Doug Bogart

ISO



Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend


ISO

BUMP ON [355150]

MULTI PRESS SMP2 - SEGMENT MAKER PRESS 2 (S/N M-5963)

Hydraulic System

MOBIL DTE 26 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP245269	USP235993	USP215335
Sample Date		Client Info		10 Aug 2023	03 Aug 2022	04 Aug 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	3	2
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	<1	2
Aluminum	ppm	ASTM D5185m	>20	<1	0	0
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	2	24	21
Tin	ppm		>20	0	0	0
Antimony	ppm	ASTM D5185m				0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	4
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	0	<1
Calcium	ppm	ASTM D5185m		64	139	137
Phosphorus	ppm	ASTM D5185m		327	486	459
Zinc	ppm	ASTM D5185m		539	667	663
Sulfur	ppm	ASTM D5185m		917	5304	4889
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	2	1
Sodium	ppm	ASTM D5185m		0	1	<1
Potassium	ppm	ASTM D5185m	>20	<1	0	0
Water	%	ASTM D6304	>0.05	0.009	0.028	0.019
ppm Water	ppm	ASTM D6304	>500	95.4	280.4	191.7
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	<u> </u>	<u>^</u> 26880	<u>23445</u>
Particles >6µm		ASTM D7647	>1300	<u>2217</u>	△ 2982	<u>\$\text{\scale}\$</u> 2509
Particles >14µm		ASTM D7647	>160	73	91	55
Particles >21µm		ASTM D7647	>40	14	13	6
Particles >38µm		ASTM D7647	>10	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u> </u>	<u>22/19/14</u>	<u>22/19/13</u>
FLUID DEGRADA	TION	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT



Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F:

T: (507)235-2104