


PROBLEM SUMMARY

North Plant-Crystallization Machine Id PU-2512G

Component Hydraulic System Fluid ROYAL PURPLE SYNDRAULIC 46 (20 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL	ABNORMAL	ABNORMAL		
Particles >4µm	ASTM D7647	>640	A 3232	4 334	A 7405		
Particles >6µm	ASTM D7647	>160	<u> </u>	6 26	1 214		
Oil Cleanliness	ISO 4406 (c)	>16/14/12	<u> </u>	19/16/12	2 0/17/13		


Customer Id: AJIEDD Sample No.: WC0786777 Lab Number: 05926104 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>



RECOMMENDED AC	RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component if applicable.		

HISTORICAL DIAGNOSIS



23 Jan 2023 Diag: Don Baldridge

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

13 Dec 2021 Diag: Angela Borella



We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

ISO

21 May 2021 Diag: Angela Borella

Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

North Plant-Crystallization PU-2512G

Component Hydraulic System Fluid ROYAL PURPLE SYNDRAULIC 46 (20 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0786777	WC0723602	WC0629073
Sample Date		Client Info		10 Aug 2023	23 Jan 2023	13 Dec 2021
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	<1	<1
Chromium	ppm	ASTM D5185m	>10	<1	<1	<1
Nickel	ppm	ASTM D5185m	>10	2	0	2
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>10	0	0	0
Lead	ppm	ASTM D5185m	>10	2	2	2
Copper	ppm	ASTM D5185m	>75	4	5	4
Tin	ppm	ASTM D5185m		0	0	0
Antimony	ppm	ASTM D5185m				0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES	I. I.	method	limit/base	current	history1	history2
Boron		ASTM D5185m		0	0	<1
Barium	ppm	ASTM D5185m		0 <1	0	0
	ppm			0	0	0
Molybdenum	ppm	ASTM D5185m ASTM D5185m		0	0	0
Manganese	ppm			2	2	1
Magnesium Calcium	ppm	ASTM D5185m ASTM D5185m	150	2 81	108	126
	ppm			-		594
Phosphorus Zinc	ppm	ASTM D5185m	670	526	559 698	594 704
	ppm	ASTM D5185m	000	624		
Sulfur	ppm	ASTM D5185m		17492	15547	12812
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	5	6	6
Sodium	ppm	ASTM D5185m		0	1	0
Potassium	ppm	ASTM D5185m		<1	<1	0
Water	%	ASTM D6304	>0.1	0.009	0.002	0.003
ppm Water	ppm	ASTM D6304	>1000	90.5	17.0	28.6
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		3232	4 334	▲ 7405
Particles >6µm		ASTM D7647	>160	<u> </u>	<u>▲</u> 626	<u> </u>
Particles >14µm		ASTM D7647	>40	26	34	<mark>▲</mark> 68
Particles >21µm		ASTM D7647	>10	7	10	1 7
		ACTM D7647	>3	•	4	0
Particles >38µm		ASTM D7647	20	0		
Particles >38µm Particles >71µm		ASTM D7647 ASTM D7647		0	3	0
Particles >71µm		ASTM D7647	>3	0	3	0


Report Id: AJIEDD [WUSCAR] 05926104 (Generated: 08/17/2023 11:06:37) Rev: 1


Submitted By: Alan Brittain



OIL ANALYSIS REPORT








VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	46.0	45.9	45.9	47.9
SAMPLE IMAGES	S	method	limit/base	current	history1	history2
Color						

Bottom



Report Id: AJIEDD [WUSCAR] 05926104 (Generated: 08/17/2023 11:06:37) Rev: 1

Submitted By: Alan Brittain

Page 4 of 4