

**B23352 - PRESS 2** 

GEAR OIL ISO 460 (--- QTS)

COMPONENT CONDITION SUMMARY

Area **RP-101** 

Component Gearbox

# **PROBLEM SUMMARY**

Sample Rating Trend VIS DEBRIS

No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	ATTENTION	NORMAL	
Debris	scalar	*Visual	NONE	🔺 MODER	NONE	NONE	

Customer Id: HORAUS Sample No.: WC0826161 Lab Number: 05927207 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

*To change component or sample information:* Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

RECOMMENDED A	CTIONS			
Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

### **HISTORICAL DIAGNOSIS**



### 06 Aug 2023 Diag: Jonathan Hester

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



### 07 May 2023 Diag: Wes Davis



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

### 02 Feb 2023 Diag: Wes Davis





Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

### view report





# **OIL ANALYSIS REPORT**

### Area **RP-101** Machine Id **B23352 - PRESS 2** Component

Gearbox Fluid GEAR OIL ISO 460 (--- QTS)

### DIAGNOSIS

### Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

## Wear

All component wear rates are normal.

### Contamination

Moderate concentration of visible dirt/debris present in the oil.

### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


# VIS DEBRIS


Sample Rating Trend


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0826161	WC0810183	WC0792011
Sample Date		Client Info		06 Aug 2023	06 Aug 2023	07 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ATTENTION	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	3	<1	0
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m	210	<1	<1	0
Silver		ASTM D5185m		0	0	0
	ppm		>25	0 <1		0
Aluminum	ppm	ASTM D5185m			<1	
Lead	ppm	ASTM D5185m	>100	<1	0	0
Copper	ppm	ASTM D5185m		<1	<1	0
Tin	ppm	ASTM D5185m	>25	0	0	0
Vanadium	ppm	ASTM D5185m		<1	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	50	0	0	0
Barium	ppm	ASTM D5185m	15	0	0	2
Molybdenum	ppm	ASTM D5185m	15	0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m	50	3	2	0
Calcium	ppm	ASTM D5185m	50	0	0	0
Phosphorus	ppm	ASTM D5185m	350	382	400	376
Zinc	ppm	ASTM D5185m	100	0	0	<1
Sulfur	ppm	ASTM D5185m	12500	272	251	43
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	14	9	12
Sodium	ppm	ASTM D5185m		4	1	0
Potassium	ppm	ASTM D5185m	>20	3	2	<1
Water	%	ASTM D6304		0.055		
ppm Water	ppm	ASTM D6304		550		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000		▲ 11760	5085
Particles >6µm		ASTM D7647	>2500		▲ 2826	1773
Particles >14µm		ASTM D7647	>320		166	164
Particles >21µm		ASTM D7647			49	44
Particles >38µm		ASTM D7647	>20		5	2
Particles >71µm		ASTM D7647	>4		0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/15		▲ 21/19/15	20/18/15
		( )				
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.85	0.39	0.37	0.37



# **OIL ANALYSIS REPORT**









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	LIGHT
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	🔺 MODER	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	0.2%	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	460	655	702	706
SAMPLE IMAGES		method	limit/base	current	history1	history2
				- (22)*		

Color



Bottom





Contact/Location: RYAN LOWE - HORAUS