

# **PROBLEM SUMMARY**


# ANDEROL 46 KAESER 1023 - US PIPE

Compressor

ANDEROL S-46 (--- GAL)

# Sample Rating Trend **WEAR**

#### **COMPONENT CONDITION SUMMARY**



#### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ATTENTION	NORMAL	NORMAL				
Copper	ppm	ASTM D5185m	>50	<b>44</b>	6	29				

Customer Id: UCATLSAL **Sample No.:** UAC05929753 Lab Number: 05929753 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

#### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

#### HISTORICAL DIAGNOSIS

### 03 Jan 2023 Diag: Angela Borella

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

# view report

#### 23 Aug 2022 Diag: Don Baldridge

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

# View report

#### 03 May 2022 Diag: Angela Borella

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

### Sample Rating Trend




# ANDEROL 46 Machine Id KAESER 1023 - US PIPE

Component

Compressor

ANDEROL S-46 (--- GAL)



### DIAGNOSIS

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

The copper level is marginal.

#### Contamination

There is no indication of any contamination in the

#### **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Aug2021	Dec2021 May2022	Aug2022 Jan2023	Aug2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UAC05929753	UCH05735088	UCH05629035
Sample Date		Client Info		11 Aug 2023	03 Jan 2023	23 Aug 2022
Machine Age	hrs	Client Info		51659	46767	43732
Oil Age	hrs	Client Info		4868	8338	5303
Oil Changed		Client Info		Not Changd	Changed	Not Changd
Sample Status				ATTENTION	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	0	0
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	<1	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>10	0	0	0
Lead	ppm	ASTM D5185m	>10	2	0	<1
Copper	ppm	ASTM D5185m	>50	<b>44</b>	6	29
Tin	ppm	ASTM D5185m	>10	<1	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	<1
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	0	0
Calcium	ppm	ASTM D5185m		0	0	0
Phosphorus	ppm	ASTM D5185m	1303	132	207	258
Zinc	ppm	ASTM D5185m		30	20	24
Sulfur	ppm	ASTM D5185m	718	412	334	284
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	0	<1	<1
Sodium	ppm	ASTM D5185m		0	<1	0
Potassium	ppm	ASTM D5185m	>20	<1	0	0
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.05	0.53	0.59	0.58
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG

Contact/Location: BILL RIMER - UCATLSAL



## **OIL ANALYSIS REPORT**







Laboratory Sample No. Lab Number Unique Number : 10615024 Test Package : IND 2

: UAC05929753 : 05929753

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 23 Aug 2023 Diagnostician : Jonathan Hester

: 21 Aug 2023

ATLANTIC COMPRESSORS

2144 SALEM INDUSTRIAL DRIVE SALEM, VA

US 24153 Contact: BILL RIMER

bill@atlanticcompressors.com T: (540)728-1147

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (757)216-0134 Contact/Location: BILL RIMER - UCATLSAL