

# **OIL ANALYSIS REPORT**

KANSAS/44/EG - DOZER

# -2014 Ap2016 Ju2016 Ju2017 Hox2017 Sep2018 Fe2020 God220 Me2022 Ap20

Sample Rating Trend




NORMAL

MO

### 36.31L [KANSAS^44^EG - DOZER] Component Diesel Engine

MOBIL DELVAC 1300 SUPER15W40 (--- GAL)



## DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor.

### Wear

All component wear rates are normal.

### Contamination


There is no indication of any contamination in the oil.


### Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



# **OIL ANALYSIS REPORT**





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	14	12.8	13.2	13.2
GRAPHS						

Ferrous Alloys

