

Area WCLSNC Machine Id QC230801HY

Component Hydraulic System Fluid JOHN DEERE HY-GARD HYD/TRANS (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL	ABNORMAL	ABNORMAL			
Particles >4µm	ASTM D7647	>5000	A 372512	A 312429	A 270750			
Particles >6µm	ASTM D7647	>1300	🔺 282737	1 38204	123762			
Particles >14µm	ASTM D7647	>160	<u> </u>	A 816	6 59			
Particles >21µm	ASTM D7647	>40	<u> </u>	15	14			
Oil Cleanliness	ISO 4406 (c)	>19/17/14	A 26/25/22	▲ 25/24/17	▲ 25/24/17			

Customer Id: WEACARQA Sample No.: WC0844500 Lab Number: 05932135 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		

HISTORICAL DIAGNOSIS



21 Aug 2023 Diag: Jonathan Hester

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

view report

18 Aug 2023 Diag: Jonathan Hester



We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

17 Aug 2023 Diag: Jonathan Hester

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

Machine Id QC230801HY

Component Hydraulic System

JOHN DEERE HY-GARD HYD/TRANS (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



Sample Rating Trend

ISO

Report Id: WEACARQA [WUSCAR] 05932135 (Generated: 08/28/2023 19:09:17) Rev: 1



OIL ANALYSIS REPORT

Color

Bottom







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	MODER	MODER	MODER
Debris	scalar	*Visual	NONE	NONE	NONE	HEAVY
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	57.0	62.1	62.5	62.2
Visc @ 100°C	cSt	ASTM D445	9.4	9.2	9.2	9.1
Viscosity Index (VI)	Scale	ASTM D2270	147	126	125	123
SAMPLE IMAGES		method	limit/base	current	history1	history2



