


PROBLEM SUMMARY

KAESER 7909253


Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status			ABNORMAL	ABNORMAL						
Particles >6µm	ASTM D7647	>1300	^ 2624	<u></u> 6558						
Particles >14µm	ASTM D7647	>80	419	274						
Particles >21µm	ASTM D7647	>20	<u> </u>	<u>45</u>						
Oil Cleanliness	ISO 4406 (c)	>/17/13	A 20/19/16	A 21/20/15						

Customer Id: AMACARLA Sample No.: KC05935411 Lab Number: 05935411 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

14 Oct 2022 Diag: Don Baldridge

ISO



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Samp



ISO



Machine Id

KAESER 7909253

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			0ct2022	Aug ² 023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KC05935411	KC102194	
Sample Date		Client Info		07 Aug 2023	14 Oct 2022	
Machine Age	hrs	Client Info		6074	3611	
Oil Age	hrs	Client Info		0	3611	
Oil Changed		Client Info		N/A	Changed	
Sample Status				ABNORMAL	ABNORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	<1	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	0	0	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>2	0	0	
Aluminum	ppm	ASTM D5185m	>10	0	1	
Lead	ppm	ASTM D5185m	>10	0	<1	
Copper	ppm	ASTM D5185m	>50	4	6	
Tin	ppm	ASTM D5185m	>10	0	<1	
Vanadium	ppm	ASTM D5185m		<1	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	
Barium	ppm	ASTM D5185m	90	<1	30	
Molybdenum	ppm	ASTM D5185m	0	0	0	
Manganese	ppm	ASTM D5185m		0	<1	
Magnesium	ppm	ASTM D5185m	100	78	64	
Calcium	ppm	ASTM D5185m	0	0	3	
Phosphorus	ppm	ASTM D5185m	0	0	4	
Zinc	ppm	ASTM D5185m	0	0	6	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	0	<1	
Sodium	ppm	ASTM D5185m		11	17	
Potassium	ppm	ASTM D5185m	>20	<1	6	
Water	%	ASTM D6304	>0.05	0.039	0.033	
ppm Water	ppm	ASTM D6304	>500	390.0	336.1	
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		5303	17117	
Particles >6µm		ASTM D7647	>1300	<u>^</u> 2624	<u>▲</u> 6558	
Particles >14μm		ASTM D7647	>80	<u>419</u>	<u>^</u> 274	
Particles >21µm		ASTM D7647		<u> </u>	4 5	
Particles >38μm		ASTM D7647	>4	2	1	
Particles >71μm		ASTM D7647	>3	0	1	
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u>20/19/16</u>	<u>\$\rightarrow\$ 21/20/15</u>	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Acid Number (AN)


mg KOH/g ASTM D8045 1.0

0.31

0.37



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Test Package

Unique Number

: KC05935411 : 05935411 : 10620682 : IND 2

Received Diagnosed Diagnostician

: 25 Aug 2023 : 28 Aug 2023 : Don Baldridge 3620 NW EVANGELINE THRWY CARENCRO, LA US 70501

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: