


# **PROBLEM SUMMARY**

# LOFT Machine Id B59523 - COMP 9 (S/N APIS44642001) Component

Compressor Fluid

# ATLAS COPCO ROTO XTEND (--- GAL)

# COMPONENT CONDITION SUMMARY



## RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

																															1							50				
Ľ																																				-						
																															1											
I																															1							_				
ľ																																					L					
ł				ł	÷																																					1
			1		-														1																		ľ					
		è					è	ŀ										İ	1											è												
	1			l	h	5		h	5	è	ć	1	h	ć	r	h	ò	[	I	h	h	è	h	1	è	ć	r		ò	[												

PROBLEMATIC TE	ST RESULTS				
Sample Status			ATTENTION	ATTENTION	NORMAL
Particles >4µm	ASTM D7647	>10000	<u> </u>	5375	1234
Particles >6µm	ASTM D7647	>1300	<u> </u>	🔺 1456	257
Oil Cleanliness	ISO 4406 (c)	>20/17/14	<u> </u>	🔺 20/18/13	17/15/10

Customer Id: HORFREWC Sample No.: WC0826136 Lab Number: 05936103 Test Package: IND 2



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

*To change component or sample information:* Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS

### 25 May 2023 Diag: Don Baldridge



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 30 Jan 2023 Diag: Don Baldridge



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

#### 02 Nov 2022 Diag: Don Baldridge



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

# LOFT Machine Id B59523 - COMP 9 (S/N APIS44642001) Component

**Compressor** 

ATLAS COPCO ROTO XTEND (--- GAL)

# DIAGNOSIS

## A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

# Wear


All component wear rates are normal.

## Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

## Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0826136	WC0775028	WC0638921
Sample Date		Client Info		01 Aug 2023	25 May 2023	30 Jan 2023
Machine Age	hrs	Client Info		59517	57884	55153
Oil Age	hrs	Client Info		6844	5211	2480
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				ATTENTION	ATTENTION	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	0	<1
Chromium	ppm	ASTM D5185m	>5	0	0	0
Nickel	ppm	ASTM D5185m		<1	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>15	0	0	0
Lead	ppm	ASTM D5185m	>65	<1	0	0
Copper	ppm	ASTM D5185m	>65	<1	<1	0
Tin	ppm	ASTM D5185m	>10	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		1	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	<1	0
Calcium	ppm	ASTM D5185m		<1	0	<1
Phosphorus	ppm	ASTM D5185m		10	3	11
Zinc	ppm	ASTM D5185m		2	<1	0
Sulfur	ppm	ASTM D5185m		18	13	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>35	0	0	0
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	1	1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	<b>12480</b>	5375	1234
Particles >6µm		ASTM D7647	>1300	<u> </u>	<u> </u>	257
Particles >14µm		ASTM D7647	>160	61	79	10
B		ASTM D7647	>40	15	21	2
Particles >21µm						
Particles >38µm		ASTM D7647	>10	0	1	0
Particles >38µm Particles >71µm		ASTM D7647 ASTM D7647	>3	0	0	0
Particles >38µm		ASTM D7647				
Particles >38µm Particles >71µm		ASTM D7647 ASTM D7647	>3	0	0	0




# **OIL ANALYSIS REPORT**










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	46	50.2	50.2	50.2
SAMPLE IMAGES	S	method	limit/base	current	history1	history2
Color				. 6.		

Bottom



 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 jas

 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x:

T: (402)753-3434

Certificate L2367