

# **PROBLEM SUMMARY**




# CONSTRUCTORS, INC Machine Id CATERPILLAR 131718

Component

Hydraulic System
Fluid

MOBIL ATF (--- GAL)

#### **Sample Rating Trend**





**COMPONENT CONDITION SUMMARY** 

No relevant graphs to display

#### RECOMMENDATION

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal.. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	NORMAL	
White Metal	scalar	*Visual	NONE	MODER	NONE	NONE	

Customer Id: CONLINNE Sample No.: SBP0004624 Lab Number: 05936418 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

#### **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

#### HISTORICAL DIAGNOSIS

### 11 May 2023 Diag: Jonathan Hester

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

#### 08 Jul 2022 Diag: Jonathan Hester

#### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

# view report

#### 06 Aug 2020 Diag: Wes Davis

#### NORMAL



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.






# **OIL ANALYSIS REPORT**



# CONSTRUCTORS, INC CATERPILLAR 131718

**Hydraulic System** MOBIL ATF (--- GAL)





#### **DIAGNOSIS**

#### Recommendation

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal.. Resample at the next service interval to monitor.

#### Wear

Moderate concentration of visible metal present. All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the


#### **Fluid Condition**

The condition of the oil is acceptable for the time in

ี						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		SBP0004624	SBP0004463	SBP0001417
Sample Date		Client Info		22 Aug 2023	11 May 2023	08 Jul 2022
Machine Age	hrs	Client Info		6408	5840	4812
Oil Age	hrs	Client Info		568	3099	2071
Oil Changed		Client Info		Changed	Changed	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	9	11	13
Chromium	ppm	ASTM D5185m	>10	0	<1	0
Nickel	ppm	ASTM D5185m	>10	0	<1	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>10	3	0	<1
Lead	ppm	ASTM D5185m	>10	0	<1	<1
Copper	ppm	ASTM D5185m	>75	5	8	8
Tin	ppm	ASTM D5185m	>10	0	0	<1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		17	24	14
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		<1	<1	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		7	12	5
Calcium	ppm	ASTM D5185m		543	939	533
Phosphorus	ppm	ASTM D5185m		674	707	640
Zinc	ppm	ASTM D5185m		399	731	598
Sulfur	ppm	ASTM D5185m		2971	2273	2376
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	2	3	2
Sodium	ppm	ASTM D5185m		2	2	3
Potassium	ppm	ASTM D5185m	>20	0	2	<1
Chlorine	ppm	ASTM D5185m				
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	o o a i a i			NONE		
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML





## **OIL ANALYSIS REPORT**




FLUID PROPERT	TES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	34	43.0	43.5	42.9
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

#### **GRAPHS**









Certificate L2367

Laboratory Sample No. Lab Number Test Package : FLEET

Unique Number : 10621689

: SBP0004624 : 05936418

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 Aug 2023 Diagnosed : 29 Aug 2023 Diagnostician : Don Baldridge

Constructors Inc. - 603659 1815 Y Street

Lincoln, NE US 68508

Contact: Jack Linhart jackl@constructorslincoln.com

T: (402)434-2157

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)