

PROBLEM SUMMARY

Sample Rating Trend






TM 7 BLEND CHEST AGITATOR


Gearbox

GEAR OIL ISO 220 (--- GAL)





COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. Inspect/change air breather if applicable. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE			
Iron	ppm	ASTM D5185m	>200	631			
Water	%	ASTM D6304	>0.2	0.229			
ppm Water	ppm	ASTM D6304	>2000	2295.2			
Appearance	scalar	*Visual	NORML	MILKY			
Free Water	scalar	*Visual		10.0			

Customer Id: KIMMOBTM7 **Sample No.:** RP0034358 Lab Number: 05937913 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.	
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.	
Resample			?	We recommend an early resample to monitor this condition.	
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.	
Check Water Access			?	We advise that you check for the source of water entry.	

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT



TM 7 BLEND CHEST AGITATOR

Gearbox

GEAR OIL ISO 220 (--- GAL)





DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. Inspect/change air breather if applicable. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

Wear

Gear wear is indicated.

Contamination

Appearance is milky. Excessive free water present. There is a light concentration of water present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0034358		
Sample Date		Client Info		28 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	631		
Chromium	ppm	ASTM D5185m	>15	3		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	2		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	0		
Tin	ppm	ASTM D5185m	>25	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	50	<1		
Barium	ppm	ASTM D5185m	15	0		
Molybdenum	ppm	ASTM D5185m	15	0		
Manganese	ppm	ASTM D5185m		2		
Magnesium	ppm	ASTM D5185m	50	<1		
Calcium	ppm	ASTM D5185m	50	<1		
Phosphorus	ppm	ASTM D5185m	350	479		
Zinc	ppm	ASTM D5185m	100	0		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	3		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
Water	%	ASTM D6304	>0.2	△ 0.229		
ppm Water	ppm	ASTM D6304	>2000	2295.2		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.85	1.07		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	MODER		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	▲ MILKY		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	0.2%		
Free Water	scalar	*Visual		(<u> </u>	1: BRAD SNOW	- KIMMOBTM7



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number Test Package : IND 2

: RP0034358 : 05937913 : 10628525

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 29 Aug 2023 : 30 Aug 2023 Diagnostician : Angela Borella

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Kimberly-Clark - Mobile - TM 7

200 BAYBRIDGE RD MOBILE, AL US 36610

Contact: BRAD SNOW brad.snow@kcc.com

T: F: (251)452-6335

Contact/Location: BRAD SNOW - KIMMOBTM7