

OIL ANALYSIS REPORT





NORMAL

LS 1 (S/N S0127RFMFLHAA03) Component

Refrigeration Compressor

CHEVRON CAPELLA OIL WF 68 (--- GAL)

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


0952
2018
AL
story2
story2
story2
)3
story2
6
1
8/13
story2
8
ORC


Report Id: CARFORCO [WUSCAR] 05938340 (Generated: 08/31/2023 12:59:32) Rev: 1




OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	VLITE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.01	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	64.0	71.6	74.6	68.21
SAMPLE IMAGES	S	method	limit/base	current	history1	history2
Color						
Bottom						



Contact/Location: ? ? - CARFORCO