

OIL ANALYSIS REPORT

Area CHEATHAM ANNEX Machine Id 1A 1ATL CRANE 1A (S/N 62510224) Component

Gearbox

MOBIL MOBILGEAR 600 XP 220 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

The water content is negligible. There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



Sample Rating Trend

NORMAL



OIL ANALYSIS REPORT


213

217

li

214





Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Ř

Submitted By: TARMO MAGI

Page 2 of 2