


# **OIL ANALYSIS REPORT**

# CHEATHAM ANNEX Machine Id 2A 2AHW CRANE 2A (S/N 62510226)

Component

Gearbox

SHELL OMALA S4 WE 220 (--- GAL)





## DIAGNOSIS

## Recommendation

Resample at the next service interval to monitor.

#### Moor

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the oil


## **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0752736	WC0573876	WC0573801
Sample Date		Client Info		01 Oct 2023	22 Jan 2023	24 Apr 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	5	2	5
Chromium	ppm	ASTM D5185m		0	<1	<1
Nickel	ppm	ASTM D5185m	>15	0	6	2
Titanium	ppm	ASTM D5185m	>10	0	0	0
Silver	ppm	ASTM D5185m		0	<1	<1
Aluminum	ppm	ASTM D5185m	<b>\25</b>	4	<1	1
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m		0	0	<1
Tin	ppm	ASTM D5185m	>200	<1	<1	<1
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m	70	0	<1	<1
Cadmium	ppm	ASTM D5185m		0	<1	<1
	ррпп			-		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	4
Barium	ppm	ASTM D5185m		0	<1	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		5	<1	0
Calcium	ppm	ASTM D5185m		0	2	2
Phosphorus	ppm	ASTM D5185m		733	582	707
Zinc	ppm	ASTM D5185m		0	2	0
Sulfur	ppm	ASTM D5185m		441	310	379
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	5	4	6
Sodium	ppm	ASTM D5185m		0	6	2
Potassium	ppm	ASTM D5185m	>20	4	1	2
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.21	0.26	0.30
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	South Gitted By	TARI© MAGI




# **OIL ANALYSIS REPORT**










# **GRAPHS**













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : IND 2

: WC0752736 : 05965501 : 10672052

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 29 Sep 2023 : 02 Oct 2023 Diagnosed Diagnostician : Don Baldridge

**CARGOTEC MARINE - MACGREGOR** 525 BYRON ST, SUITE B

CHESAPEAKE, VA US 23320

Contact: TARMO MAGI

tarmo.magi@macgregor.com T: (757)558-4584

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (757)558-4581