

PROBLEM SUMMARY


Area **Utility** FEH85AH11 Cooling Tower, Cell/Fan Gearbox

Gearbox

JAX FGG-AW ISO 220 (8 GAL)

Sample Rating Trend ISO

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL						
Particles >4µm	ASTM D7647	>20000	137267						
Particles >6µm	ASTM D7647	>5000	40242						
Oil Cleanliness	ISO 4406 (c)	>21/19/16	4 24/23/13						

Customer Id: NOVFRANC Sample No.: WC0822455 Lab Number: 05966274 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component if applicable.			

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Area **Utility** FEH85AH11 Cooling Tower, Cell/Fan Gearbox

Gearbox

JAX FGG-AW ISO 220 (8 GAL)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0822455		
Sample Date		Client Info		28 Sep 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	32		
Chromium	ppm	ASTM D5185m	>15	0		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	0		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		3		
Phosphorus	ppm	ASTM D5185m		672		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		586		
CONTAMINANTS	1	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	13		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
Water	%	ASTM D6304	>0.2	0.001		
ppm Water	ppm	ASTM D6304	>2000	3.1		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	137267		
Particles >6µm		ASTM D7647	>5000	40242		
Particles >14µm		ASTM D7647	>640	80		
Particles >21µm		ASTM D7647	>160	13		
Particles >38µm		ASTM D7647	>40	0		
Particles >71µm		ASTM D7647	>10	0		
Oil Cleanliness		ISO 4406 (c)	>21/19/16	24/23/13		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
	1/011/	ACTM DOOM		0.65		

0.65

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: 10672825

: WC0822455 : 05966274

Received Diagnosed

: 02 Oct 2023 : 03 Oct 2023

Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF, PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

P.O. BOX 576, 77 PERRY CHAPEL CHURCH ROAD FRANKLINTON, NC

US 27525

Contact: BRUCE THOMAS brct@novozymes.com

T: (919)494-3146 F: (919)494-3456