


PROBLEM SUMMARY

Area **RP-101** Machine Id **B57004 - SOUTH DISCHARGE SCREW (S/N 10023277475)** Component **Gearbox** Fluid

PETRO CANADA ENDURATEX EP 320 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL	ABNORMAL	NORMAL		
Particles >4µm	ASTM D7647	>10000	<u> </u>	2 0491	9557		
Particles >6µm	ASTM D7647	>2500	🔺 2960	2099	1089		
Oil Cleanliness	ISO 4406 (c)	>20/18/15	<u> </u>	A 22/18/13	20/17/12		


Customer Id: HORAUS Sample No.: WC0808568 Lab Number: 05967756 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED A	ENDED ACTIONS						
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Resample			?	We recommend an early resample to monitor this condition.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			

HISTORICAL DIAGNOSIS



17 Jun 2023 Diag: Don Baldridge

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

13 Jan 2022 Diag: Wes Davis

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





27 Sep 2021 Diag: Wes Davis

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are notably high. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Area **RP-101** Machine Id **B57004 - SOUTH DISCHARGE SCREW (S/N 10023277475)** Component

Gearbox Fluid

PETRO CANADA ENDURATEX EP 320 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0808568	WC0814178	WC0610644
Sample Date		Client Info		27 Sep 2023	17 Jun 2023	13 Jan 2022
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	27	22	18
Chromium	ppm	ASTM D5185m	>15	<1	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	0	0	0
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	<1	<1	0
Tin	ppm	ASTM D5185m	>25	0	0	0
Antimony	ppm	ASTM D5185m	>5			0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	55	26	30	22
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m	0	<1	0	1
Calcium	ppm	ASTM D5185m		<1	0	<1
Phosphorus	ppm	ASTM D5185m	240	406	452	506
Zinc	ppm	ASTM D5185m	1	6	0	8
Sulfur	ppm	ASTM D5185m	13700	5505	6493	6221
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<1	<1	<1
Sodium	ppm	ASTM D5185m		<1	<1	0
Potassium	ppm	ASTM D5185m	>20	<1	0	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	A 24510	2 0491	9557
Particles >6µm		ASTM D7647	>2500	<u> </u>	2099	1089
Particles >14µm		ASTM D7647	>320	83	73	40
Particles >21µm		ASTM D7647	>80	27	16	7
Particles >38µm		ASTM D7647	>20	3	1	0
Particles >71µm		ASTM D7647	>4	0	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/15	<u>/</u> 22/19/14	🔺 22/18/13	20/17/12
Oil Cleanliness		ISO 4406 (c) method	>20/18/15 limit/base	22/19/14 current	22/18/13 history1	20/17/12 history2



Acid Number

an3/1

lan3/16

Mar20/17

Aar20/1

1 40

(B/H0) 1.00 E 0.80 Via Number 0.60

0.2

0.00

360

340

် 32(

300 300


28


260 Jan1/15

ŕς,

Jan


OIL ANALYSIS REPORT






VISUAL		method	limit/base	current	nistory i	nistory2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	325	324	325	326
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Oslar						





Bottom





Contact/Location: RYAN LOWE - HORAUS