


OIL ANALYSIS REPORT

TULSA [19097]

40-238

Component **Swing Drive**

CONOCO PHILLIPS GUARDOL ECT 15W40





Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition


The condition of the oil is acceptable for the time in service.

(GAL)		L	,	lug2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0818617		
Sample Date		Client Info		28 Aug 2023		
Machine Age	hrs	Client Info		3145		
Oil Age	hrs	Client Info		3145		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>400	15		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	3		
Lead	ppm	ASTM D5185m	>50	0		
Copper	ppm	ASTM D5185m	>200	<1		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	85	8		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		4		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	350	26		
Calcium	ppm	ASTM D5185m	1800	4210		
Phosphorus	ppm	ASTM D5185m	1000	929		
Zinc	ppm	ASTM D5185m	1100	1131		
Sulfur	ppm	ASTM D5185m	3500	6743		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	15		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		
. ree rraie.						

Page 1 of 2





OIL ANALYSIS REPORT




SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image

GRAPHS











Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10675022 Test Package : CONST

: WC0818617 : 05968471

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 03 Oct 2023 Diagnosed : 04 Oct 2023 Diagnostician : Doug Bogart

MANHATTAN ROAD AND BRIDGE

5601 S 122ND E AVE TULSA, OK US 74146

Contact: JAMES STEELMON james.steelmon@manhattanrb.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: