

PROBLEM SUMMARY

Sample Rating Trend

ISO

Machine Id


KAESER BSD 60 8233385 (S/N 1176)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	NORMAL					
Particles >6µm	ASTM D7647	>1300	2845	1277					
Particles >14µm	ASTM D7647	>80	188	70					
Particles >21µm	ASTM D7647	>20	△ 30	7					
Oil Cleanliness	ISO 4406 (c)	>/17/13	20/19/15	19/17/13					

Customer Id: EASALL Sample No.: KC111082 Lab Number: 05981233 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

Action Status Date Done By Description Change Fluid --- ? Oil and filter change at the time of sampling has been noted. Change Filter --- ? Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

01 Mar 2023 Diag: Doug Bogart

NORMAL



Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend

ISO

KAESER BSD 60 8233385 (S/N 1176)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			Mar2023	Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KC111082	KC101044	
Sample Date		Client Info		22 Aug 2023	01 Mar 2023	
Machine Age	hrs	Client Info		6273	4168	
Oil Age	hrs	Client Info		6273	4168	
Oil Changed		Client Info		Changed	Changed	
Sample Status				ABNORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	0	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	0	0	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>2	0	0	
Aluminum	ppm	ASTM D5185m	>10	1	<1	
Lead	ppm	ASTM D5185m	>10	0	0	
Copper	ppm	ASTM D5185m	>50	10	11	
Tin	ppm	ASTM D5185m	>10	0	0	
Vanadium	ppm	ASTM D5185m		0	<1	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	
Barium	ppm	ASTM D5185m	90	0	0	
Molybdenum	ppm	ASTM D5185m		0	0	
Manganese	ppm	ASTM D5185m		0	<1	
Magnesium	ppm	ASTM D5185m	90	10	16	
Calcium	ppm	ASTM D5185m	2	0	0	
Phosphorus	ppm	ASTM D5185m		0	0	
Zinc	ppm	ASTM D5185m		15	37	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1	<1	
Sodium	ppm	ASTM D5185m		9	6	
Potassium	ppm	ASTM D5185m	>20	4	3	
Water	%	ASTM D6304	>0.05	0.014	0.012	
ppm Water	ppm	ASTM D6304	>500	145.9	123.7	
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647		6811	3265	
Particles >6µm		ASTM D7647	>1300	<u> </u>	1277	
Particles >14µm		ASTM D7647	>80	<u> </u>	70	
Particles >21µm		ASTM D7647	>20	<u>^</u> 30	7	
Particles >38µm		ASTM D7647	>4	1	1	
Particles >71µm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u>^</u> 20/19/15	19/17/13	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

0.36

Acid Number (AN)


mg KOH/g ASTM D8045 0.4

0.40

Contact/Location: SERVICE MANAGER - EASALL



OIL ANALYSIS REPORT







Certificate L2367

Sample No. Lab Number **Unique Number** Test Package

: KC111082 : 05981233

: 10698528 : IND 2

: 17 Oct 2023 Received Diagnosed

: 19 Oct 2023 Diagnostician : Jonathan Hester 601 S. 10TH STREET ALLENTOWN, PA

US 18103

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: