

PROBLEM SUMMARY


Sample Rating Trend

WATER

KAESER SX 5 5670810 (S/N 1565)


Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL	ATTENTION		
Water	%	ASTM D6304	>0.05	△ 0.114	0.008	0.009		
ppm Water	ppm	ASTM D6304	>500	<u> </u>	83.7	90		
Silt	scalar	*Visual	NONE	MODER	NONE	NONE		

Customer Id: SURBET Sample No.: KC94450 Lab Number: 05981239 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

HISTORICAL DIAGNOSIS

19 Aug 2020 Diag: Jonathan Hester

ISO



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



01 Feb 2019 Diag: Jonathan Hester

ISO



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



30 May 2018 Diag: Angela Borella

ISO




We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



KAESER SX 5 5670810 (S/N 1565)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We recommend an early resample in 500 hours to monitor this condition.

All component wear rates are normal.

Contamination

There is a light concentration of water present in the oil. There is a moderate amount of visible silt present in the sample.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		Oct2017	May2018	Feb2019 Aug2020	Sep2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KC94450	KC83153	KC69553
Sample Date		Client Info		08 Sep 2023	19 Aug 2020	01 Feb 2019
Machine Age	hrs	Client Info		1362	819	523
Oil Age	hrs	Client Info		200	300	308
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ATTENTION
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	<1	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	<1	0
Aluminum	ppm	ASTM D5185m	>10	0	0	0
Lead	ppm	ASTM D5185m	>10	0	<1	<1
Copper	ppm	ASTM D5185m	>50	<1	1	<1
Tin	ppm	ASTM D5185m	>10	0	<1	0
Antimony	ppm	ASTM D5185m			0	0
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	0
Barium	ppm	ASTM D5185m	90	0	8	18
Molybdenum	ppm	ASTM D5185m		0	<1	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m	90	0	14	48
Calcium	ppm	ASTM D5185m	2	0	8	<1
Phosphorus	ppm	ASTM D5185m		0	12	<1
Zinc	ppm	ASTM D5185m		12	13	23
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	0	4	<1
Sodium	ppm	ASTM D5185m		<1	0	11
Potassium	ppm	ASTM D5185m	>20	0	<1	0
Water	%	ASTM D6304	>0.05	△ 0.114	0.008	0.009
ppm Water	ppm	ASTM D6304	>500	1140	83.7	90
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647			21279	4226
Particles >6µm		ASTM D7647	>1300		<u>11431</u>	▲ 1822
Particles >14µm		ASTM D7647	>80		▲ 777	1 33
Particles >21µm		ASTM D7647	>20		<u>^</u> 74	2 9
Particles >38µm		ASTM D7647	>4		1	1
Particles >71µm		ASTM D7647	>3		0	0
Oil Cleanliness		ISO 4406 (c)	>/17/13		<u>▲</u> 21/17	△ 18/14
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	0.08	0.144	0.259



OIL ANALYSIS REPORT











Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package

: KC94450 : 05981239

ś

: 10698534 : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 17 Oct 2023 Received Diagnosed : 24 Oct 2023

Aug 19/20

Diagnostician : Jonathan Hester **REYNOLDS & REYNOLDS**

2501 BAGLYOS CIRCLE BETHLEHEM, PA US 18020

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F:

history2

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

history2

NEG

NEG

43.83 history2