




FUEL REPORT

Sample Rating Trend



WATER



Machine Id
FAST-C
 Component
Tank Gasoline
 Fluid
NOT GIVEN (--- GAL)

DIAGNOSIS

▲ Recommendation

This is a baseline read-out on the submitted sample.

▲ Contamination

There is a light concentration of water present in the gasoline.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0869454	---	---
Sample Date	Client Info		11 Oct 2023	---	---
Machine Age	hrs	Client Info	0	---	---
Oil Age	hrs	Client Info	0	---	---
Oil Changed	Client Info		N/A	---	---
Sample Status			ABNORMAL	---	---

CONTAMINANTS


	method	limit/base	current	history1	history2
Water	%	ASTM D6304	<0.05	▲ 0.217	---
ppm Water	ppm	ASTM D6304	<500	▲ 2172.2	---
% Gasoline	%	*In-House	<0.50	100.0	---
% Biodiesel	%	*In-House	<20.0	0.0	---

SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image



FUEL REPORT



GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0869454
Lab Number : 05981569
Unique Number : 10698864
Test Package : DF-2 (Additional Tests: API, CC Flash, Cetane, Color-ASTM, Fuel, GC-PercFuel, ICP, KF, KV40, Pri

VITAL FUEL SYSTEMS
 1076 CLASSIC RD
 APEX, NC
 US 27539

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: JOHN MORREALE
 jmorreale@vitalfuelsystems.com

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)629-8180
 F: (919)303-7399