

PROBLEM SUMMARY

TM 11 Machine Id TM 11 PRESSURE ROLL REDUCER

Gearbox

ROYAL PURPLE SYNERGY 90/220 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL	SEVERE	SEVERE		
Particles >4µm	ASTM D7647	>20000	<u> </u>	137565	47342		
Particles >6µm	ASTM D7647	>5000	41343	🛑 14216	<u> </u>		
Particles >14µm	ASTM D7647	>640	<u> </u>	41	594		
Particles >21µm	ASTM D7647	>160	6 592	6	110		
Oil Cleanliness	ISO 4406 (c)	>21/19/16	<u> </u>	• 24/21/13	23/20/16		

Customer Id: KIMMOBTM11 Sample No.: RP0034371 Lab Number: 05994352 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED ACT	ECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component if applicable.			

HISTORICAL DIAGNOSIS



05 May 2023 Diag: Don Baldridge

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

30 Mar 2022 Diag: Doug Bogart



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

08 Oct 2021 Diag: Doug Bogart

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

TM 11 TM 11 PRESSURE ROLL REDUCER Component

Gearbox Fluid

ROYAL PURPLE SYNERGY 90/220 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0034371	RP0023580	RP0016705
Sample Date		Client Info		08 Aug 2023	05 May 2023	30 Mar 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		14	23	
Iron	ppm	ASTM D5185m	>200	67	62	65
Chromium	ppm	ASTM D5185m	>15	<1	0	<1
Nickel	ppm	ASTM D5185m	>15	<1	0	<1
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	4	2	8
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	2	<1	1
Tin	ppm	ASTM D5185m	>25	<1	0	0
Antimony	ppm	ASTM D5185m	>5			
Vanadium	maa	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		22	19	19
Barium	ppm	ASTM D5185m		19	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m		<1	0	0
Phosphorus	ppm	ASTM D5185m	370	238	232	238
Zinc	ppm	ASTM D5185m		26	0	6
CONTAMINANTS	i	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	3	3	3
Sodium	ppm	ASTM D5185m		3	2	<1
Potassium	ppm	ASTM D5185m	>20	0	0	0
Water	%	ASTM D6304	>0.2	0.016	0.013	0.009
ppm Water	ppm	ASTM D6304	>2000	165.1	130.6	97.6
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	129997	137565	47342
Particles >6µm		ASTM D7647	>5000	<u> </u>	• 14216	▲ 7352
Particles >14µm		ASTM D7647	>640	A 1992	41	594
Particles >21µm		ASTM D7647	>160	<u> </u>	6	110
Particles >38µm		ASTM D7647	>40	29	1	6
Particles >71µm		ASTM D7647	>10	2	1	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	4/23/18	• 24/21/13	23/20/16
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	ma KOH/a	ASTM D8045	1.33	1.52	1 59	1 1 4

Acid Number (AN) Report Id: KIMMOBTM11 [WUSCAR] 05994352 (Generated: 11/01/2023 16:11:20) Rev: 1

mg KOH/g ASTM D8045 1.33

Contact/Location: LARRY WEAVER - KIMMOBTM11



PQ

0

12000

10000

6000

4000

200

26

24

180

160

14

Water (ppm)

OIL ANALYSIS REPORT

VISUAL





White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	216.1	229	229	234
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color					Phase Phase	

limit/base

current

method



history1

history2

Bottom

GRAPHS

