


# **OIL ANALYSIS REPORT**

### Sample Rating Trend







# KANSAS/15/EG - EXCAVATOR 20.142L [KANSAS^15^EG - EXCAVATOR]

Component
Rear Right Final Drive

**MOBIL MOBILTRANS HD 50 (**-

### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

ID 50 ( GAL)		Dec2017	Jan2019 May2021	Feb2022 Jan2023	Oct2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0833859	WC0746085	WC0741834
Sample Date		Client Info		13 Oct 2023	08 Jun 2023	18 Jan 2023
Machine Age	hrs	Client Info		6095	5820	5413
Oil Age	hrs	Client Info		275	4489	4637
Oil Changed		Client Info		Not Changd	Changed	Not Chango
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	23	86	54
Chromium	ppm	ASTM D5185m	>10	0	0	<1
Nickel	ppm	ASTM D5185m	>5	<1	<1	<1
Titanium	ppm	ASTM D5185m	>15	<1	<1	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>75	2	2	3
Lead	ppm	ASTM D5185m	>10	1	0	<1
Copper	ppm	ASTM D5185m	>75	<1	0	<1
Tin	ppm	ASTM D5185m	>8	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		3	4	2
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		1	1	2
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		40	25	25
Calcium	ppm	ASTM D5185m		2963	3229	2850
Phosphorus	ppm	ASTM D5185m		1093	1072	923
Zinc	ppm	ASTM D5185m		1293	1373	1217
Sulfur	ppm	ASTM D5185m		7403	10491	9276
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	11	25	16
Sodium	ppm	ASTM D5185m		3	4	2
Potassium	ppm	ASTM D5185m	>20	1	4	2
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	TIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	195	194	200	201




## **OIL ANALYSIS REPORT**







### **GRAPHS**



### Non-ferrous Metals









Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10723122 Test Package : CONST

: WC0833859 : 05994762

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 31 Oct 2023 Diagnosed : 01 Nov 2023 Diagnostician : Don Baldridge

SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213 Contact: DOUG KING

doug.king@sherwood.net T: (316)617-3161

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: SHEWIC [WUSCAR] 05994762 (Generated: 11/01/2023 20:05:10) Rev: 1

Submitted By: WENDY DUNSON

F: x: