

FUEL REPORT

[NORTH TX CONTRACTING] Washine Id VOLVO SD45B 230569

Component **Diesel Fuel**

NOT GIVEN (--- GAL)

Sample Rating Trend NORMAL October 1

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time.

Corrosion

All metal levels are normal indicating no corrosion in the system.

Contaminants

The water content is negligible. There is no indication of any contamination in the fuel.


Fuel Condition


The condition of the fuel is acceptable for the time in service.

				Oct2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		VCP408720		
Sample Date		Client Info		25 Oct 2023		
Machine Age	hrs	Client Info		65		
Sample Status				NORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		2.82		
SULFUR CONTE	٧T	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	<1		
Sodium	ppm	ASTM D5185m	< 0.1	3		
Potassium	ppm	ASTM D5185m	< 0.1	<1		
Water	%	ASTM D6304	< 0.05	0.002		
ppm Water	ppm	ASTM D6304	< 500	24.3		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0		
Nickel	ppm	ASTM D5185m	<0.1	<1		
Lead	ppm	ASTM D5185m	< 0.1	<1		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	< 0.1	0		
Calcium	ppm	ASTM D5185m	<0.1	3		
Magnesium	ppm	ASTM D5185m	<0.1	0		
Phosphorus	ppm	ASTM D5185m	< 0.1	3		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



FUEL REPORT







Certificate L2367

Report Id: VOLVO0081 [WUSCAR] 05994825 (Generated: 11/03/2023 13:22:02) Rev: 1

Laboratory Sample No. Lab Number Unique Number : 10723185

: VCP408720 : 05994825

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 31 Oct 2023 Diagnosed : 03 Nov 2023 Diagnostician : Jonathan Hester

Test Package : MOB 1 (Additional Tests: KF, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

ROMCO INC 1350 NE LOOP 820 FORT WORTH, TX US 76106

Contact: ROB HOLCOMB rholcomb@romco.com T: (817)798-9289 F: (817)626-8983

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)