


Hydraulic System


Machine Id MP Component

PROBLEM SUMMARY



CASTROL HYSPIN AWS HYDRAULIC 46 (300 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL			
Copper	ppm	ASTM D5185m	>20	<u> </u>			
Particles >4µm		ASTM D7647	>5000	<u> </u>			
Particles >6µm		ASTM D7647	>1300	<u> </u>			
Particles >14µm		ASTM D7647	>160	<u> </u>			
Particles >21µm		ASTM D7647	>40	🔺 144			
Oil Cleanliness		ISO 4406 (c)	>19/17/14	A 21/19/16			

Customer Id: NEUBOS Sample No.: WC05995550 Lab Number: 05995550 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 <u>jhester@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		
Resample			?	We recommend an early resample to monitor this condition.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

WEAR

Machine Id MP Component

Hydraulic System

CASTROL HYSPIN AWS HYDRAULIC 46 (300 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

🔺 Wear

The copper level is abnormal. All other component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC05995550		
Sample Date		Client Info		30 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0		
Chromium	ppm	ASTM D5185m	>20	0		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	0		
Lead	ppm	ASTM D5185m	>20	0		
Copper	ppm	ASTM D5185m	>20	<u> </u>		
Tin	ppm	ASTM D5185m	>20	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		1		
Calcium	ppm	ASTM D5185m		45		
Phosphorus	ppm	ASTM D5185m		253		
Zinc	ppm	ASTM D5185m		383		
Sulfur	ppm	ASTM D5185m		978		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<u> 16202</u>		
Particles >6µm		ASTM D7647	>1300	<u> </u>		
Particles >14µm		ASTM D7647	>160	<u> </u>		
Particles >21µm		ASTM D7647	>40	🔺 144		
Particles >38µm		ASTM D7647	>10	4		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	1 21/19/16		
FLUID DEGRADA		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.30		



OIL ANALYSIS REPORT

scalar

scalar

method


*Visual


*Visual

VISUAL

White Metal

Yellow Metal







limit/base

NONE

NONE

NONE


current


NONE


NONE

history1

history2







Certificate L2367

Contact/Location: AUSTIN BAKER - NEUBOS