


PROBLEM SUMMARY


OMNILUBE 46 XL ATLAS COPCO API622136 - HEARTHSIDE FOOD SOLUTIONS

Component Compressor





COMPONENT CONDITION SUMMARY



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS											
Sample Status				ATTENTION	ATTENTION	NORMAL					
Visc @ 40°C	cSt	ASTM D445	41.2	△ 67.4	△ 62.4	55.2					

Customer Id: UCAIRSID Sample No.: UCH05995811 Lab Number: 05995811 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1

don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

01 Oct 2022 Diag: Doug Bogart

VISCOSITY



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Confirm oil type. The AN level is acceptable for this fluid.



10 Jun 2022 Diag: Jonathan Hester

NORMAL



We suspect abnormal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

13 Mar 2022 Diag: Aaron Black

VISCOSITY



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Confirm oil type. The AN level is acceptable for this fluid.






OIL ANALYSIS REPORT

OMNILUBE 46 XL ATLAS COPCO API622136 - HEARTHSIDE FOOD SOLUTIONS

Component







DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The oil viscosity is higher than normal. Confirm oil type. The AN level is acceptable for this fluid.


Nov2019 Apr2020 Feb2021 Jun2021 Jan2022 Jun2022 0-x2023							
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2	
Sample Number		Client Info		UCH05995811	UCH05665776	UCH05593887	
Sample Date		Client Info		18 Oct 2023	01 Oct 2022	10 Jun 2022	
Machine Age	hrs	Client Info		50700	0	39288	
Oil Age	hrs	Client Info		50700	0	39288	
Oil Changed		Client Info		N/A	N/A	N/A	
Sample Status				ATTENTION	ATTENTION	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2	
Iron	ppm	ASTM D5185m	>50	0	0	0	
Chromium	ppm	ASTM D5185m	>5	0	0	0	
Nickel	ppm	ASTM D5185m		0	0	0	
Titanium	ppm	ASTM D5185m		0	0	0	
Silver	ppm	ASTM D5185m		0	0	0	
Aluminum	ppm	ASTM D5185m	>15	0	1	<1	
Lead	ppm	ASTM D5185m	>65	0	0	0	
Copper	ppm	ASTM D5185m		<1	<1	<1	
Tin	ppm	ASTM D5185m	>10	0	0	0	
Vanadium	ppm	ASTM D5185m	710	0	<1	0	
Cadmium	ppm	ASTM D5185m		0	0	0	
ADDITIVES		method	limit/base	current	history1	history2	
Boron	ppm	ASTM D5185m		0	0	0	
Barium	ppm	ASTM D5185m		0	0	0	
Molybdenum	ppm	ASTM D5185m		0	0	0	
Manganese	ppm	ASTM D5185m		0	<1	0	
Magnesium	ppm	ASTM D5185m		0	0	0	
Calcium	ppm	ASTM D5185m		0	0	0	
Phosphorus		ASTM D5185m	75	5	15	4	
Zinc	ppm		75	5 <1	0	0	
Sulfur	ppm	ASTM D5185m	1500				
	ppm	ASTM D5185m		110	0	231	
CONTAMINANTS		method	limit/base	current	history1	history2	
Silicon	ppm	ASTM D5185m	>35	<1	<1	0	
Sodium	ppm	ASTM D5185m		<1	0	0	
Potassium	ppm	ASTM D5185m	>20	2	0	<1	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2	
Acid Number (AN)	mg KOH/g	ASTM D8045	0.24	1.48	1.17	0.69	
VISUAL		method	limit/base	current	history1	history2	
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	MODER	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	NEG	




OIL ANALYSIS REPORT










GRAPHS













Laboratory Sample No. Lab Number

: UCH05995811 : 05995811 Unique Number : 10724171 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 01 Nov 2023 Diagnosed : 02 Nov 2023 Diagnostician : Don Baldridge

AIR HANDLING EQUIPMENT INC

1389 RIVERSIDE DR SIDNEY, OH US 45365 Contact: CRISTI CURL

cristi@ahequip.net

F: (937)492-3147

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)