

## **PROBLEM SUMMARY**

Area [84123] G8

Component


**Hydraulic System** 

**MILITARY MIL-L-5606A (40 GAL)** 

# Sample Rating Trend



### **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status		ABNORMAL	NORMAL	NORMAL			
Particles >4µm	ASTM D7647 >5	6000 <b>A 12042</b>	982	3773			
Particles >6µm	ASTM D7647 >1	300 <b>A 3082</b>	258	1120			
Particles >14µm	ASTM D7647 >1	<b>60 △ 232</b>	19	154			
Particles >21µm	ASTM D7647 >4	<b>64 △</b>	3	42			
Oil Cleanliness	ISO 4406 (c) >1	9/17/14 <b>21/19/15</b>	17/15/11	19/17/14			

Customer Id: NORPLAMA **Sample No.:** WC0789380 Lab Number: 05996268 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample			?	We recommend an early resample to monitor this condition.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

### HISTORICAL DIAGNOSIS

### 26 Apr 2023 Diag: Angela Borella

### NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



### 16 Sep 2022 Diag: Doug Bogart

### NORMAL



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

## view report

### 29 Mar 2022 Diag: Angela Borella

### NORMAL



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





**OIL ANALYSIS REPORT** 

Area [84123] G8

Component

**Hydraulic System** 

**MILITARY MIL-L-5606A (40 GAL)** 

# Sample Rating Trend



### **DIAGNOSIS**

### Recommendation

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.

### Wear

All component wear rates are normal.

### Contamination

There is a moderate amount of particulates (2 to 100 microns in size) present in the oil.


### **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		Sep2017	Dec2020 Mar2022	Sep2022 Apr2023	Oct2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0789380	WC0723455	WC0609161
Sample Date		Client Info		25 Oct 2023	26 Apr 2023	16 Sep 2022
Machine Age	yrs	Client Info		0	0	0
Oil Age	yrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0	0	0
Chromium	ppm	ASTM D5185m	>20	0	<1	0
Nickel	ppm	ASTM D5185m	>20	0	<1	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	0	0
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	<1	0	<1
Tin	ppm	ASTM D5185m	>20	0	1	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	0
Magnesium	ppm	ASTM D5185m		<1	2	0
Calcium	ppm	ASTM D5185m		5	2	5
Phosphorus	ppm	ASTM D5185m		400	462	423
Zinc	ppm	ASTM D5185m		13	0	14
Sulfur	ppm	ASTM D5185m		174	174	226
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	<1	<1
Sodium	ppm	ASTM D5185m		<1	4	<1
Potassium	ppm	ASTM D5185m	>20	4	1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	<u> </u>	982	3773
Particles >6µm		ASTM D7647	>1300	<u> </u>	258	1120
Particles >14μm		ASTM D7647	>160	<u>^</u> 232	19	154
Particles >21µm		ASTM D7647		<u>^</u> 64	3	42
Particles >38μm		ASTM D7647	>10	5	0	3
Particles >71μm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u> </u>	17/15/11	19/17/14
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.058	0.198	0.091



## **OIL ANALYSIS REPORT**




VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
ELLUD DDODEDT	150		11 11 /1		1111	1:


- Fartic	ie irenu				
30k <del>-</del>					
5.	_ Aum 1				
≘ <sup>25k</sup> -	Gum				
E	1.4				
	14µm				
S ZUK +	**				
sponed to be a departed to departed to be a departed to be a departed to be a departed to b	***				
₫ 15k +					
40	1				4
5 10k +					
물		4.			
≥ 5k + Abnorma	d i	<b>N</b> . 1		i	
JK T G THE IN	***				- martin
01		N 40 10 10 10 10 10 10 10 10 10 10 10 10 10	-		<b>医放射性医型型性</b> 结核
0k <del>L =====</del>			300000000000000000000000000000000000000	TO THE PERSON NAMED IN COLUMN	
5	72/	72/	72	72	72
ep26/1	65	23	9	pr26/	)ct25
- E	ă	Mar29,	8	후	5
0,0		_		-	

FLUID PROPER	RTIES	method	limit/base	current	history1	histor
Visc @ 40°C	cSt	ASTM D445		15.5	15.5	15.9


SAMPLE IMAGES method limit/base current Color







**Bottom GRAPHS** 







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : IND 2

: 10724628

To discuss this sample report, contact Customer Service at 1-800-237-1369.

ś

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0789380 : 05996268

Received Diagnosed Diagnostician

: 01 Nov 2023 : 03 Nov 2023 : Wes Davis

**NORTHLAND-WILLETTE INC** 

12 HIGH ST PLAINVILLE, MA US 02762

Contact: JIM ALLEN

JALLEN@NWHYDINC.COM

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (508)699-4017

T: