

OIL ANALYSIS REPORT

Sample Rating Trend







Machine Id **625138**

Component **Diesel Engine**

Fluid

VALVOLINE 15W40 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear

Metal levels are typical for a new component breaking in.

Contamination

There is no indication of any contamination in the


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

			Nov2022	0ct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		IL0034274	IL05701264	
Sample Date		Client Info		17 Oct 2023	08 Nov 2022	
Machine Age	mls	Client Info		51248	33351	
Oil Age	mls	Client Info		0	0	
Oil Changed		Client Info		Changed	N/A	
Sample Status				NORMAL	NORMAL	
CONTAMINATION	V	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	
Glycol		WC Method		NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	15	36	
Chromium	ppm	ASTM D5185m	>20	1	2	
Nickel	ppm	ASTM D5185m	>4	0	0	
Titanium	ppm	ASTM D5185m		0	<1	
Silver	ppm	ASTM D5185m	>3	0	0	
Aluminum	ppm	ASTM D5185m	>20	14	29	
Lead	ppm	ASTM D5185m	>40	0	0	
Copper	ppm	ASTM D5185m	>330	<1	4	
Tin	ppm	ASTM D5185m	>15	0	<1	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		<1	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	39	117	82	
Barium	ppm	ASTM D5185m	1	<1	<1	
Molybdenum	ppm	ASTM D5185m	49	72	79	
Manganese	ppm	ASTM D5185m	1	0	1	
Magnesium	ppm	ASTM D5185m	616	603	675	
Calcium	ppm	ASTM D5185m	1554	1149	1285	
Phosphorus	ppm	ASTM D5185m	899	782	658	
Zinc	ppm	ASTM D5185m	1069	914	835	
Sulfur	ppm	ASTM D5185m	2624	2767	2722	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	7	9	
Sodium	ppm	ASTM D5185m		0	3	
Potassium	ppm	ASTM D5185m	>20	12	55	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.6	1	
Nitration	Abs/cm	*ASTM D7624	>20	8.4	11.8	
Sulfation	Abs/.1mm	*ASTM D7415	>30	20.3	25.0	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.8	20.3	
Base Number (BN)	mg KOH/g	ASTM D2896		7.8	8.2	
2000 Harribor (D/V)	mg nong	. IO THI DEGGO	0.0		0.2	





OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	
FLUID PROPER	ΓIES	method	limit/base	current	history1	history2

I LOID I NOI LITTILS		memou			i ilistory i	HISTOLYZ
Visc @ 100°C	cSt	ASTM D445	13.6	12.8	12.6	













Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10724806

: IL0034274 : 05996446 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 02 Nov 2023 Diagnosed : 02 Nov 2023

Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) TAMPA IDEALEASE 5951 ORIENT ROAD TAMPA, FL

US 33610-9565 Contact: Russ Cook russcook@idealease.com

T: (813)626-9285 F: (844)270-1356