

PROBLEM SUMMARY


Preparation-Prep CBL MILL

[Preparation-Prep CBL MILL] 360006002 - CBL MILL BUSHING LUBE UNIT

Component Lube System

SHELL MORLINA S3 BA 220 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS											
Sample Status				ABNORMAL	ABNORMAL						
Copper	ppm	ASTM D5185m	>20	<u> </u>	A 36						
White Metal	scalar	*Visual	NONE	🔺 MODER	LIGHT						


Customer Id: MICAND Sample No.: TLC0001090 Lab Number: 05998148 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

11 Jul 2023 Diag: Jonathan Hester



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Area Preparation-Prep CBL MILL [Preparation-Prep CBL MILL] 360006002 - CBL MILL BUSHING LUBE UNIT Component

Lube System

SHELL MORLINA S3 BA 220 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

📥 Wear


The copper level is abnormal. Moderate concentration of visible metal present.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		TLC0001090	TLC0001190	
Sample Date		Client Info		19 Oct 2023	11 Jul 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				ABNORMAL	ABNORMAL	
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		14	13	
Iron	ppm	ASTM D5185m	>20	0	0	
Chromium	ppm	ASTM D5185m	>20	<1	0	
Nickel	ppm	ASTM D5185m	>20	<1	<1	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>20	2	0	
Lead	ppm	ASTM D5185m	>20	- 16	13	
Copper	ppm	ASTM D5185m	>20	<u> </u>	▲ 36	
Tin	ppm	ASTM D5185m	>20	5	4	
Vanadium		ASTM D5185m	20	0	0	
Cadmium	ppm	ASTM D5185m		0	0	
	ppm			-	-	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	
Barium	ppm	ASTM D5185m		19	0	
Molybdenum	ppm	ASTM D5185m		0	0	
Manganese	ppm	ASTM D5185m		0	<1	
Magnesium	ppm	ASTM D5185m		<1	0	
Calcium	ppm	ASTM D5185m		<1	<1	
Phosphorus	ppm	ASTM D5185m		39	3	
Zinc	ppm	ASTM D5185m		8	0	
Sulfur	ppm	ASTM D5185m		6292	6945	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	7	4	
Sodium	ppm	ASTM D5185m		0	0	
Potassium	ppm	ASTM D5185m	>20	<1	2	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.05	0.16	0.13	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	A MODER	LIGHT	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	
Free Water	scalar	*Visual	- 0.00	NEG		DUSTY LOLLIS
1100 1100	ooului	Violati		1120	Contractor Dy.	



OIL ANALYSIS REPORT



Page 4 of 4