


# **OIL ANALYSIS REPORT**

# ULTRA COOLANT [SVO-056577] Machine Id INGERSOLL RAND CBV241227 - ALLOY WHEEL

Component

Compressor





### DIAGNOSIS

## Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

## Contamination

There is no indication of any contamination in the oil


# **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			Apr2022	0 ct 2 0 2 3		
SAMPLE INFORM	MATION	method	limit/base	ourront	hiotonyl	hiotony2
	IATION		IIIIII/Dase	current	history1	history2
Sample Number		Client Info		UCH05999138	UCH05537449	
Sample Date		Client Info		25 Oct 2023	29 Apr 2022	
Machine Age	hrs	Client Info		18888	15937	
Oil Age	hrs	Client Info		600	0	
Oil Changed		Client Info		Not Changd	N/A	
Sample Status				NORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1	1	
Chromium	ppm	ASTM D5185m	>10	<1	0	
Nickel	ppm	ASTM D5185m		<1	<1	
Titanium	ppm	ASTM D5185m		<1	<1	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>25	<1	<1	
Lead	ppm	ASTM D5185m	>25	<1	0	
Copper	ppm	ASTM D5185m	>50	<1	<1	
Tin	ppm	ASTM D5185m	>15	0	<1	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		<1	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	2	
Barium	ppm	ASTM D5185m	556	520	584	
Molybdenum	ppm	ASTM D5185m		0	0	
Manganese	ppm	ASTM D5185m		0	0	
Magnesium	ppm	ASTM D5185m		<1	<1	
Calcium	ppm	ASTM D5185m	242	2	3	
Phosphorus	ppm	ASTM D5185m	0	9	10	
Zinc	ppm	ASTM D5185m	0	12	12	
Sulfur	ppm	ASTM D5185m	306	252	368	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	1	2	
Sodium	ppm	ASTM D5185m		23	29	
Potassium	ppm	ASTM D5185m	>20	4	3	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.2	0.18	0.23	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	LIGHT	LIGHT	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	
7:36:31) Rov: 1			044	Location: BACH	EL VONLLATTE	N HOLOHOV



# **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10727498

: UCH05999138 : 05999138 Test Package : IND 2

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 06 Nov 2023 Diagnosed : 07 Nov 2023 Diagnostician : Angela Borella

JOHN HENRY FOSTER COMPANY

4700 LEBOURGET STREET SAINT LOUIS, MO

US 63134 Contact: RACHEL VON HATTEN

> rvonhatten@jhf.com T: (314)593-1267 F: (314)874-0965

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)