

FUEL REPORT

Sample Rating Trend

NORMAL

Area **Store 9 - Marietta** Machine Id **JOHN DEERE 160G 111821 (S/N 1FF160GXLMF058316)** Component

Diesel Fuel

NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time.

Corrosion

All metal levels are normal indicating no corrosion in the system.

Contaminants

The water content is negligible. There is no indication of any contamination in the fuel.

Fuel Condition

The condition of the fuel is acceptable for the time in service.








SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		LEC0028835		
Sample Date		Client Info		31 Oct 2023		
Machine Age	hrs	Client Info		951		
Sample Status				NORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		2.54		
SULFUR CONTEI	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		320		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0		
Sodium	ppm	ASTM D5185m	<0.1	1		
Potassium	ppm	ASTM D5185m	<0.1	0		
Water	%	ASTM D6304	<0.05	0.005		
ppm Water	ppm	ASTM D6304	<500	59.0		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0		
Nickel	ppm	ASTM D5185m	<0.1	0		
Lead	ppm	ASTM D5185m	<0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	<0.1	0		
Calcium	ppm	ASTM D5185m	<0.1	4		
Magnesium	ppm	ASTM D5185m	<0.1	0		
Phosphorus	ppm	ASTM D5185m	<0.1	1		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



FUEL REPORT







Contact/Location: ROSS OGLEBEE - BRIBRIOH