


PROBLEM SUMMARY


OCEAN VOYAGER Machine Id [OCEAN VOYAGER] OCEAN VOYAGER STEERING PT

Port Steering

CASTROL HYSPIN AWH-M ISO 32 (40 LTR)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST	RESULTS				
Sample Status			ATTENTION	NORMAL	NORMAL
Particles >4µm	ASTM D7647	>2500	<u> </u>	791	1532
Particles >6µm	ASTM D7647	>640	△ 688	138	278
Oil Cleanliness	ISO 4406 (c)	>18/16/13	19/17/13	17/14/10	18/15/12

Customer Id: VICNEWIN Sample No.: WC0824866 Lab Number: 06006268 Test Package: MAR 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

03 Oct 2023 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.



03 Sep 2022 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.



01 Jul 2022 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.






OIL ANALYSIS REPORT

OCEAN VOYAGER [OCEAN VOYAGER] OCEAN VOYAGER STEERING PT

Component

Port Steering

CASTROL HYSPIN AWH-M ISO 32 (40 LTR)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the fluid.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.

Doc2021 Jul2022 Smp2022 Oct2023 Oct2023						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0824866	WC0824579	WC0693025
Sample Date		Client Info		30 Oct 2023	03 Oct 2023	03 Sep 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>60	6	22	7
Chromium	ppm	ASTM D5185m	>12	0	<1	0
Nickel	ppm	ASTM D5185m	>6	0	0	0
Γitanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>4	0	2	0
_ead	ppm	ASTM D5185m	>12	<1	<1	0
Copper	ppm	ASTM D5185m	>30	6	5	6
Γin	ppm	ASTM D5185m		<1	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		1	2	0
Calcium	ppm	ASTM D5185m		117	126	138
Phosphorus	ppm	ASTM D5185m		418	388	439
Zinc	ppm	ASTM D5185m		537	510	551
Sulfur	ppm	ASTM D5185m		3234	3847	4143
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>10	1	<1	<1
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	0	<1	0
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	▲ 3295	791	1532
Particles >6µm		ASTM D7647	>640	△ 688	138	278
Particles >14µm		ASTM D7647	>80	47	9	22
Particles >21µm		ASTM D7647	>20	11	3	9
Particles >38µm		ASTM D7647	>4	1	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>18/16/13	1 9/17/13	17/14/10	18/15/12
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.68	0.52	0.58



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No.

Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0824866 : 06006268

: 10740030

Received : 13 Nov 2023 Diagnosed

: 14 Nov 2023 Diagnostician : Doug Bogart

Test Package : MAR 2 (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

American Queen Voyages - Oceans

1201 Bridgeport Drive Jeffersonville, IN US 47130

Contact: Dietrich Giles

DIETRICH.GILES@AQVOYAGES.COM

T: (228)591-6239

Contact/Location: Dietrich Giles - VICNEWIN

F: