

## **PROBLEM SUMMARY**

Sample Rating Trend




KAESER 5537539

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

## **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status			ATTENTION	ABNORMAL						
Particles >6µm	ASTM D7647	>1300	<b>1399</b>							
Oil Cleanliness	ISO 4406 (c)	>/17/13	<b>20/18/13</b>							

Customer Id: CEDSANCA Sample No.: KCPA003804 Lab Number: 06006348 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

## HISTORICAL DIAGNOSIS

## 17 May 2021 Diag: Don Baldridge

VIS DEBRIS



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





## **OIL ANALYSIS REPORT**

Sample Rating Trend

ISO

# **KAESER 5537539**

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

## **DIAGNOSIS**

#### Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

### Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

#### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				<u></u>		
			May2021	Nov2023		
SAMPLE INFORM	ΙΔΤΙΩΝ	method	limit/base	current	history1	history2
	711014		IIIIII Dasc			
Sample Number		Client Info		KCPA003804	KCP31837	
Sample Date	laa	Client Info		07 Nov 2023	17 May 2021	
Machine Age	hrs	Client Info		17358	11279	
Oil Age	hrs	Client Info		0 N/A	3502	
Oil Changed Sample Status		Client Info		ATTENTION	Changed ABNORMAL	
				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	<1	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	0	0	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>2	0	0	
Aluminum	ppm	ASTM D5185m	>10	0	0	
Lead	ppm	ASTM D5185m	>10	0	0	
Copper	ppm	ASTM D5185m	>50	11	12	
Tin	ppm	ASTM D5185m	>10	0	0	
Antimony	ppm	ASTM D5185m			0	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	<1	
Barium	ppm	ASTM D5185m	90	0	0	
Molybdenum	ppm	ASTM D5185m	0	0	0	
Manganese	ppm	ASTM D5185m		0	0	
Magnesium	ppm	ASTM D5185m	100	0	<1	
Calcium	ppm		0	0	0	
Phosphorus	ppm	ASTM D5185m	0	<1	1	
Zinc	ppm	ASTM D5185m	0	0	11	
Sulfur	ppm	ASTM D5185m	23500	17060	15990	
CONTAMINANTS		method	limit/base	current	history1	history2
		ASTM D5185m				motory
Silicon	ppm	ASTM D5185m	>23	0	0	
Sodium	ppm		. 20	<1	0	
Potassium	ppm	ASTM D5185m	>20	0	0.004	
Water ppm Water	% ppm	ASTM D6304 ASTM D6304	>0.05 >500	0.006 62.0	46.9	
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647		7729		
Particles >6μm		ASTM D7647	>1300	<u> </u>		
Particles >14μm		ASTM D7647	>80	45		
Particles >21µm		ASTM D7647	>20	11		
Particles >38μm		ASTM D7647	>4	0		
Particles >71μm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u>^</u> 20/18/13		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	ma 1/011/a	ACTM DOOM	1.0	0.36	0.351	



## **OIL ANALYSIS REPORT**





Sample No. Lab Number **Unique Number** 

: KCPA003804

: 06006348 : 10740110

Received : 13 Nov 2023 Diagnosed

: 14 Nov 2023 Diagnostician : Doug Bogart

Test Package : IND 2 ( Additional Tests: KF, PrtCount ) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

2401 AGNEW RD SANTA CLARA, CA US 95054

Contact: JASON ELDRIDGE

jasoneldridge@cagreatamerica.com

T: F: