

FUEL REPORT

Sample Rating Trend

NORMAL



SLOATSBURG PUMP STATION 16701001888

Component Diesel Fuel

NOT GIVEN (--- GAL)

Recommendation

This is a baseline read-out on the submitted sample.

				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0834434		
Sample Date		Client Info		11 Oct 2023		
Machine Age	hrs	Client Info		280		
Sample Status				NORMAL		
SULFUR CONTE	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		10		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0		
Sodium	ppm	ASTM D5185m	<0.1	<1		
Potassium	ppm	ASTM D5185m	<0.1	0		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0		
Nickel	ppm	ASTM D5185m	<0.1	0		
Lead	ppm	ASTM D5185m	< 0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	< 0.1	0		
Calcium	ppm	ASTM D5185m	<0.1	0		
Magnesium	ppm	ASTM D5185m	< 0.1	0		
Phosphorus	ppm	ASTM D5185m	<0.1	<1		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGES	5	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



FUEL REPORT



Certificate L2367

Laboratory Sample No.

Lab Number Unique Number : 10740415 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0834434 Received : 06006653 Diagnosed

: 13 Nov 2023 : 16 Nov 2023 Diagnostician : Jonathan Hester

US 12553 Contact: JOE SAYEGH To discuss this sample report, contact Customer Service at 1-800-237-1369. joe@gentechltd.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (845)568-0500 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (845)568-3073

GEN TECH LTD

NEW WINDSOR, NY

3017 RT 9W