

## **FUEL REPORT**

### Sample Rating Trend

## NORMAL



# LIME KILN PUMP STATION D190554491

Component Diesel Fuel

NOT GIVEN (--- GAL)

## Recommendation

This is a baseline read-out on the submitted sample.

SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0834486		
Sample Date		Client Info		12 Oct 2023		
Machine Age	hrs	Client Info		83		
Sample Status				NORMAL		
SULFUR CONTE	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0		
Sodium	ppm	ASTM D5185m	< 0.1	<1		
Potassium	ppm	ASTM D5185m	<0.1	0		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	< 0.1	0		
Nickel	ppm	ASTM D5185m	< 0.1	0		
Lead	ppm	ASTM D5185m	< 0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	<0.1	0		
Calcium	ppm	ASTM D5185m	< 0.1	0		
Magnesium	ppm	ASTM D5185m	<0.1	0		
Phosphorus	ppm	ASTM D5185m	< 0.1	<1		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGE	S	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



## **FUEL REPORT**



Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10740419

: WC0834486 : 06006657 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 16 Nov 2023 Diagnostician : Jonathan Hester

: 13 Nov 2023

3017 RT 9W NEW WINDSOR, NY US 12553 Contact: JOE SAYEGH joe@gentechltd.com

**GEN TECH LTD** 

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (845)568-0500 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (845)568-3073