

OIL ANALYSIS REPORT

Sample Rating Trend


DIRT



DECM01BE (S/N ZBA01290) Component

Biogas Engine

CHEVRON HDAX 6500 LFG GAS ENGINE OIL (100 GAL)



DIAGNOSIS

Recommendation

We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

🔺 Wear

The iron level is abnormal.

Contamination

Elemental level of silicon (Si) above normal.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The AN level is acceptable for this fluid.

Submitted By: JEFF SUMMERS

Page 1 of 2




Number

% final

OIL ANALYSIS REPORT





May19/23 1016/73 Aug2/23

Certificate L2367

Unique Number

Test Package

: 10742276

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Diagnostician : Doug Bogart

: MOB 2 (Additional Tests: FuelDilution, PercentFuel)

Submitted By: JEFF SUMMERS

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

13.2

lav19/23