


## **PROBLEM SUMMARY**


## OKLAHOMA/105/EG - TRUCK-ON-HWY-HEAVY DUTY Machine Id 08.95 [OKLAHOMA^105^EG - TRUCK-ON-HWY-HEAVY DUTY]


Component Hydraulic System

## MOBIL MOBILFLUID 424 (--- GAL)

### COMPONENT CONDITION SUMMARY







#### RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

### PROBLEMATIC TEST RESULTS

THOBEENMIN						
Sample Status				ABNORMAL	ABNORMAL	NORMAL
Copper	ppm	ASTM D5185m	>75	<u> </u>	6	39
Particles >6µm		ASTM D7647	>2500	<b>A</b> 10532		103
Oil Cleanliness		ISO 4406 (c)	>/18/16	<u> </u>		19/14/10

Customer Id: SHEWIC Sample No.: WC0874058 Lab Number: 06009059 Test Package: CONST



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED	MMENDED ACTIONS				
Action	Status	Date	Done By	Description	
Change Fluid			?	Oil and filter change at the time of sampling has been noted.	
Change Filter			?	Oil and filter change at the time of sampling has been noted.	

#### HISTORICAL DIAGNOSIS



#### 05 Oct 2021 Diag: Jonathan Hester

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to metal particles present in this sample. The iron level is abnormal. The aluminum level is abnormal. Moderate concentration of visible metal present. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type. The AN level is acceptable for this fluid.



#### 08 Sep 2018 Diag: Don Baldridge

#### NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





## **OIL ANALYSIS REPORT**

#### Area OKLAHOMA/105/EG - TRUCK-ON-HWY-HEAVY DUTY Machine Id 08.95 [OKLAHOMA^105^EG - TRUCK-ON-HWY-HEAVY DUTY] Component

Hydraulic System

MOBIL MOBILFLUID 424 (--- GAL)

#### DIAGNOSIS

#### Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### 🔺 Wear


The copper level is abnormal. All other component wear rates are normal.

#### Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

#### Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0874058	WC0627879	WCCF0982
Sample Date		Client Info		09 Nov 2023	05 Oct 2021	08 Sep 2018
Machine Age	hrs	Client Info		10011	9448	8225
Oil Age	hrs	Client Info		563	558	2000
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m		9	<b>4</b> 1	7
Chromium	ppm	ASTM D5185m	>10	0	0	<1
Nickel	ppm	ASTM D5185m	>10	0	0	0
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>10	1	▲ 22	<1
Lead	ppm	ASTM D5185m	>10	<1	1	0
Copper	ppm	ASTM D5185m		<u> </u>	6	39
Tin	ppm	ASTM D5185m		<1	1	0
Antimony		ASTM D5185m	210	< I 	0	0
Vanadium	ppm ppm	ASTM D5185m		0	0	0
		ASTM D5185m		0	0	<1
Cadmium	ppm					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		131	116	45
Barium	ppm	ASTM D5185m		6	0	<1
Molybdenum	ppm	ASTM D5185m		1	<1	2
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		19	<b></b> 0	7
Calcium	ppm	ASTM D5185m		3800	<u> </u>	1789
Phosphorus	ppm	ASTM D5185m		1311	<u> </u>	724
Zinc	ppm	ASTM D5185m		1531	<u> </u>	877
Sulfur	ppm	ASTM D5185m		6024	▲ 829	2727
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	12	2	7
Sodium	ppm	ASTM D5185m		2	3	2
Potassium	ppm	ASTM D5185m	>20	3	<1	6
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		62427		2578
Particles >6µm		ASTM D7647	>2500	<u> </u>		103
Particles >14µm		ASTM D7647	>640	392		9
Particles >21µm		ASTM D7647	>160	80		3
Particles >38µm		ASTM D7647	>40	1		0
Particles >71µm		ASTM D7647	>10	0		0
Oil Cleanliness		ISO 4406 (c)	>/18/16	<b>A</b> 23/21/16		19/14/10
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.54	1.303	0.571




# **OIL ANALYSIS REPORT**










Color



Bottom



Submitted By: SHAWN SOUTH

Page 4 of 4