


# **OIL ANALYSIS REPORT**

WO 68
Machine Id
LL 1 - BUFFALO WATER

Component **Drive End Pump** 





### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			Sep2023	Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCH06009711	UCH05959916	
Sample Date		Client Info		15 Nov 2023	20 Sep 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				NORMAL	ATTENTION	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	3	18	
Chromium	ppm	ASTM D5185m	>5	0	0	
Nickel	ppm	ASTM D5185m	>5	0	0	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>3	0	0	
Aluminum	ppm	ASTM D5185m	>7	0	2	
Lead	ppm	ASTM D5185m	>12	0	3	
Copper	ppm	ASTM D5185m		1	3	
Tin	ppm	ASTM D5185m	>9	6	<u>^</u> 16	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	
Barium	ppm	ASTM D5185m	5	0	0	
Molybdenum	ppm	ASTM D5185m	5	0	<1	
Manganese	ppm	ASTM D5185m		0	1	
Magnesium	ppm	ASTM D5185m	5	0	<1	
Calcium	ppm	ASTM D5185m	12	0	<1	
Phosphorus	ppm	ASTM D5185m	400	575	591	
Zinc	ppm	ASTM D5185m	12	2	0	
Sulfur	ppm	ASTM D5185m	650	586	690	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm		>60	3	5	
Sodium	ppm	ASTM D5185m	00	2	2	
Potassium	ppm		>20	0	0	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.50	0.39	0.43	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	LIGHT	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>.1	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	



## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number

: UCH06009711 Unique Number : 10743473

: 06009711 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 16 Nov 2023

Diagnosed : 17 Nov 2023 Diagnostician : Doug Bogart **CORROSION PRODUCTS & EQUIPMENT INC** 110 ELMGROVE PARK

ROCHESTER, NY US 14624

Contact: Bill Cox cox@corrosion-products.com

T: (585)455-7978 F: (585)247-7268

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)