

# FUEL REPORT

Sample Rating Trend



Area [145248] Machine Id JOHN DEERE 748H 1DW748HXHED664379 Component Diesel Fuel

No.2 DIESEL FUEL (LOW-SULPHUR) (42 GAL)

# Nev\$223



NORMAL

## DIAGNOSIS Recommendation

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time. (Customer Sample Comment: checking fuel for contamination, customer suspects a possibility of tampering )

### Corrosion

All metal levels are normal indicating no corrosion in the system.

### Contaminants

The water content is negligible. There is no indication of any contamination in the fuel.

### **Fuel Condition**

The condition of the fuel is acceptable for the time in service.

SAMPLE INFORM	<u>IATI</u> ON	method	limit/base	current	history1	history2
Sample Number		Client Info		LEC0042902		
Sample Date		Client Info		15 Nov 2023		
Machine Age	hrs	Client Info		0		
Sample Status				NORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	3.0	2.37		
SULFUR CONTER	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m	250	0		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0		
Sodium	ppm	ASTM D5185m	<0.1	0		
Potassium	ppm	ASTM D5185m	<0.1	1		
Water	%	ASTM D6304	<0.05	0.006		
ppm Water	ppm	ASTM D6304	<500	65.8		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	1		
Nickel	ppm	ASTM D5185m	<0.1	0		
Lead	ppm	ASTM D5185m	<0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	0		
Iron	ppm	ASTM D5185m	<0.1	2		
Calcium	ppm	ASTM D5185m	<0.1	<1		
Magnesium	ppm	ASTM D5185m	<0.1	<1		
Phosphorus	ppm	ASTM D5185m	<0.1	9		
Zinc	ppm	ASTM D5185m	<0.1	0		
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



# **FUEL REPORT**





