

# **OIL ANALYSIS REPORT**

# Sample Rating Trend

# NORMAL

# CATERPILLAR OFF ROAD 158

**Hydraulic System** 

PETRO CANADA 10W (--- GAL)

## Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the

# **Fluid Condition**

The condition of the oil is acceptable for the time in service.

			Jun 2023	Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0868146	WC0822426	
Sample Date		Client Info		04 Nov 2023	08 Jun 2023	
Machine Age	hrs	Client Info		12635	12032	
Oil Age	hrs	Client Info		293	250	
Oil Changed		Client Info		N/A	Changed	
Sample Status				NORMAL	ABNORMAL	
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0	0	
Chromium	ppm	ASTM D5185m	>10	0	<1	
Nickel	ppm	ASTM D5185m	>10	<1	0	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m		<1	0	
Aluminum	ppm	ASTM D5185m	>10	<1	2	
Lead	ppm	ASTM D5185m	>10	<1	1	
Copper	ppm	ASTM D5185m	>75	1	4	
Tin	ppm	ASTM D5185m	>10	0	<1	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		93	90	
Barium	ppm	ASTM D5185m		0	0	
Molybdenum	ppm	ASTM D5185m		3	4	
Manganese	ppm	ASTM D5185m		<1	<1	
Magnesium	ppm	ASTM D5185m		52	54	
Calcium	ppm	ASTM D5185m		2939	3199	
Phosphorus	ppm	ASTM D5185m		1058	1055	
Zinc	ppm	ASTM D5185m		1286	1348	
Sulfur	ppm	ASTM D5185m		3043	3854	
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	7	
Sodium	ppm	ASTM D5185m		2	3	
Potassium	ppm	ASTM D5185m	>20	0	1	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	▲ MODER	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	
C 14/-1		43 C		NEO	NIEO	


scalar \*Visual


NEG

NEG



# **OIL ANALYSIS REPORT**









Certificate L2367

Laboratory Sample No. Lab Number

**Unique Number** Test Package : MOB 1

: WC0868146 : 06011783 : 10750927

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 17 Nov 2023 : 21 Nov 2023

Diagnostician : Sean Felton

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**C.L. BENTON & SONS INC** 706 38TH AVE N

MYRTLE BEACH, SC US 29577

Contact: NEIL neil@clbenton.com

no image

T: F:

Report Id: CLBMYR [WUSCAR] 06011783 (Generated: 11/21/2023 14:41:08) Rev: 1

Contact/Location: NEIL ? - CLBMYR