

No relevant graphs to display

BEC	OMN	/FND	ATI	ON
			/	

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC T	EST RE	SULTS				
Sample Status				ABNORMAL	NORMAL	NORMAL
Debris	scalar	*Visual	NONE	A MODER	NONE	VLITE

Customer Id: MILATH Sample No.: WC0761488 Lab Number: 06012346 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 <u>don.b505@comcast.net</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.		

HISTORICAL DIAGNOSIS



22 Feb 2023 Diag: Don Baldridge

Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

22 Nov 2022 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

26 Apr 2022 Diag: Don Baldridge



Resample at the next service interval to monitor.All component wear rates are normal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

Sample Rating Trend

VIS DEBRIS

Machine Id 0204 (S/N PRESS 9) Component

Hydraulic System Fluid AW HYDRAULIC OIL ISO 100 (800 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0761488	WC0701712	WC0701719
Sample Date		Client Info		16 Nov 2023	22 Feb 2023	22 Nov 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	maa	ASTM D5185m	>20	0	0	<1
Chromium	mag	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	<1	0
Lead	ppm	ASTM D5185m	>20	0	<1	<1
Copper	ppm	ASTM D5185m	>20	12	9	8
Tin	ppm	ASTM D5185m	>20	<1	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	nnm	ASTM D5185m	5	0	0	0
Barium	nnm	ASTM D5185m	5	0	0	0
Molybdenum	ppm	ASTM D5185m	5	-1	<1	-1
Manganese	nnm	ASTM D5185m	5	0	0	0
Maganesium	nnm	ASTM D5185m	25	0	4	5
Calcium	nnm	ASTM D5185m	200	62	81	79
Phosphorus	nnm	ASTM D5185m	300	353	389	400
Zinc	nnm	ASTM D5185m	370	464	517	484
Sulfur	nom	ASTM D5185m	2500	878	951	1046
	PP	mothod	limit/base	ourront	bioton/1	history?
CONTAIVIINANTS		method		current	nistory i	nistory2
Silicon	ppm	ASTM D5185m	>15	<1	<1	<1
Sodium	ppm	ASTM D5185m		<1	0	0
Potassium	ppm	ASTM D5185m	>20	0	0	0
water	%	ASTM D6304	>0.05	NEG	NEG	NEG
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000		2535	1568
Particles >6µm		ASTM D7647	>1300		720	312
Particles >14µm		ASTM D7647	>160		45	22
Particles >21µm		ASTM D7647	>40		5	8
Particles >38µm		ASTM D7647	>10		0	1
Particles >71µm		ASTM D7647	>3		0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14		19/17/13	18/15/12
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.57	0.22	0.28	0.32



OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	A MODER	NONE	VLITE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
FLUID PROPERT Visc @ 40°C	IES cSt	method ASTM D445	limit/base	current 93.1	history1 93.7	history2 93.8
FLUID PROPERT Visc @ 40°C SAMPLE IMAGES	IES cSt	method ASTM D445 method	limit/base 100 limit/base	current 93.1 current	history1 93.7 history1	history2 93.8 history2
FLUID PROPERT Visc @ 40°C SAMPLE IMAGES Color	IES cSt	method ASTM D445 method	limit/base 100 limit/base	current 93.1 current	history1 93.7 history1	history2 93.8 history2



Contact/Location: GREG INDERRIEDEN - MILATH