


PROBLEM SUMMARY

STUFFING [23667795] Machine Id LN 5 VAT DUMPER HYD - B41381

Component


Hydraulic System

PETRO CANADA HYDREX AW 46 (10 GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS											
Sample Status			ATTENTION	ABNORMAL	ABNORMAL						
Particles >6µm	ASTM D7647	>1300	<u> </u>		957						
Oil Cleanliness	ISO 4406 (c)	>-/17/14	22/18/13		▲ 18/17/15						

Customer Id: OSCOSC Sample No.: WC0866194 Lab Number: 06012389 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

19 Aug 2023 Diag: Don Baldridge

WATER



We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. There is a light concentration of water present in the oil. Moderate concentration of visible dirt/debris present in the oil. The oil viscosity is higher than normal. The AN level is acceptable for this fluid.



10 May 2023 Diag: Don Baldridge

WATER



We advise that you follow the water drain-off procedure for this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. There is a light concentration of water present in the oil. Free water present. The AN level is acceptable for this fluid.



07 Feb 2023 Diag: Jonathan Hester

WATER



We advise that you follow the water drain-off procedure for this component. Resample at the next service interval to monitor.All component wear rates are normal. Free water present. There is a light concentration of water present in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



history1

STUFFING [23667795] LN 5 VAT DUMPER HYD - B41381

Hydraulic System

PETRO CANADA HYDREX AW 46 (10 GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in



Onese la Nassala es		Oli a saturata		W00000404	W0004000	W00040000
Sample Number		Client Info		WC0866194	WC0840986	WC0810608
Sample Date		Client Info		07 Nov 2023	19 Aug 2023	10 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	5	1	2
Chromium	ppm	ASTM D5185m	>20	<1	0	<1
Nickel	ppm	ASTM D5185m	>20	0	0	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>20	0	0	<1
Lead	ppm	ASTM D5185m	>20	0	0	<1
Copper	ppm	ASTM D5185m	>20	2	<1	<1
Tin	ppm	ASTM D5185m	>20	0	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m	0	<1	0	<1
Magnesium	ppm	ASTM D5185m	0	0	0	0
Calcium	ppm	ASTM D5185m	50	0	0	2
Phosphorus	ppm	ASTM D5185m	330	419	409	525
Zinc	ppm	ASTM D5185m	430	0	0	0
Sulfur	ppm	ASTM D5185m	760	388	671	74
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	4	0	3
Sodium	ppm	ASTM D5185m		2	0	2
Potassium	ppm	ASTM D5185m	>20	0	<1	2
Water	%	ASTM D6304	>0.05	0.011	△ 0.056	△ 0.061
ppm Water	ppm	ASTM D6304	>500	115.6	▲ 560	△ 610
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		22799		1757
Particles >6µm		ASTM D7647	>1300	<u> </u>		957
Particles >14µm		ASTM D7647	>160	67		<u>▲</u> 163
Particles >21µm		ASTM D7647	>40	17		<u></u> 55
Particles >38µm		ASTM D7647	>10	0		8
Particles >71µm		ASTM D7647	>3	0		1
Oil Cleanliness		ISO 4406 (c)	>-/17/14	<u>22/18/13</u>		▲ 18/17/15
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.70	0.24	0.187	0.26



OIL ANALYSIS REPORT







Certificate L2367

Lab Number **Unique Number**

: 06012389 : 10751533

Diagnosed

: 22 Nov 2023 Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

OSCEOLA, IA US 50213

Contact: WADE MYERS wlmyers@hormel.com T: (641)342-8043

Contact/Location: WADE MYERS - OSCOSC

F: (641)342-8047