

OIL ANALYSIS REPORT


Sample Rating Trend

NORMAL



OKLAHOMA/102 74.30 [OKLAHOMA^102] Component Front Right Final Drive

MOBIL MOBILTRANS HD 50 (--- GAL)





Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

ID 30 (GAL)		May202	2 Sep2022	Dec2022 N	ov2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0821766	WC0746377	WC0738568
Sample Date		Client Info		10 Nov 2023	05 Dec 2022	10 Sep 2022
Machine Age	hrs	Client Info		2245	958	692
Oil Age	hrs	Client Info		2200	958	692
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATIO	V	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>501	75	55	37
Chromium	ppm	ASTM D5185m	>11	<1	1	<1
Nickel	ppm	ASTM D5185m	>5	<1	<1	0
Titanium	ppm	ASTM D5185m	>15	<1	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m		1	4	2
Lead	ppm	ASTM D5185m	>10	2	4	2
Copper	ppm	ASTM D5185m		40	33	32
Tin	ppm	ASTM D5185m	>8	4	3	3
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
	ррпп					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		193	171	188
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		<1	<1	<1
Manganese	ppm	ASTM D5185m		2	2	1
Magnesium	ppm	ASTM D5185m		1	2	<1
Calcium	ppm	ASTM D5185m		61	41	36
Phosphorus	ppm	ASTM D5185m		940	937	922
Zinc	ppm	ASTM D5185m		19	<1	15
Sulfur	ppm	ASTM D5185m		26571	25056	24054
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>51	3	2	1
Sodium	ppm	ASTM D5185m		0	3	2
Potassium	ppm	ASTM D5185m	>20	3	2	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	MODER	MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	VLITE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
-42:20\ Dov: 1	Journal	VISUAI		1123	Submitted Dv	





OIL ANALYSIS REPORT






GRAPHS











Certificate L2367

Laboratory Sample No. Lab Number

: WC0821766 : 06012745 Unique Number : 10751889 Test Package : CONST

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 20 Nov 2023 Diagnosed : 22 Nov 2023

Diagnostician : Jonathan Hester

SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213

Contact: SHAWN SOUTH

shawn.south@sherwood.net

T: x: F: x:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)