

# **OIL ANALYSIS REPORT**

Sample Rating Trend



Machine Id **G29** Component

Front Differential

GEAR OIL SAE 75W90 (--- GAL)

	GΝ		

## Recommendation

Resample at the next service interval to monitor. ( Customer Sample Comment: Front diff 75:90 gear oil)

## Wear

All component wear rates are normal.

# Contamination

There is no indication of any contamination in the oil.


## **Fluid Condition**

The condition of the oil is acceptable for the time in service.

				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0858174		
Sample Date		Client Info		14 Nov 2023		
Machine Age	hrs	Client Info		10405		
Oil Age	hrs	Client Info		3300		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>500	392		
Chromium	ppm	ASTM D5185m	>10	2		
Nickel	ppm	ASTM D5185m	>10	8		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>100	22		
Γin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	400	250		
Barium	ppm	ASTM D5185m	200	<1		
Molybdenum	ppm	ASTM D5185m	12	0		
Manganese	ppm	ASTM D5185m		8		
Magnesium	ppm	ASTM D5185m	12	0		
Calcium	ppm	ASTM D5185m	150	7		
Phosphorus	ppm	ASTM D5185m	1650	1406		
Zinc	ppm	ASTM D5185m	125	29		
Sulfur	ppm	ASTM D5185m	22500	23666		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	45		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	0		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Free Water	scalar	*Visual		NEG		
26·24) Rov. 1					Submitted By:	CODY COLOR



# **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: WC0858174 : 06013532 : 10752676

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 20 Nov 2023

Diagnosed : 22 Nov 2023 Diagnostician : Sean Felton

Test Package : CONST (Additional Tests: FT-IR, KV100) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Apple Valley Waste - Hometown Location

155 Airport Road Selinsgrove, PA

US 17870

T:

F:

Contact: Service Manager

Submitted By: CODY COLON