


FUEL REPORT

WESTCHESTER DEF - SPRAIN LIFT PUMP STATION

Sample Rating Trend





Diesel Fuel Fluid

NOT GIVEN (--- GAL)

Component

Recommendation

This is a baseline read-out on the submitted sample.

Corrosion

All metal levels are normal indicating no corrosion in the system.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0878310	WC0749039	WC0612479
Sample Date		Client Info		13 Nov 2023	06 Oct 2022	30 Nov 2021
Machine Age	hrs	Client Info		244	242	239
Sample Status				NORMAL	NORMAL	NORMAL
SULFUR CONTER	ΝT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0	51	23
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0	0	0
Sodium	ppm	ASTM D5185m	<0.1	<1	0	<1
Potassium	ppm	ASTM D5185m	<0.1	0	0	0
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0	0	0
Nickel	ppm	ASTM D5185m	<0.1	0	0	0
Lead	ppm	ASTM D5185m	<0.1	0	0	0
Vanadium	ppm	ASTM D5185m	<0.1	0	0	0
Iron	ppm	ASTM D5185m	<0.1	0	0	0
Calcium	ppm	ASTM D5185m	<0.1	9	15	0
Magnesium	ppm	ASTM D5185m	<0.1	0	0	0
Phosphorus	ppm	ASTM D5185m	<0.1	0	0	0
Zinc	ppm	ASTM D5185m	<0.1	0	0	0
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color						
Bottom						






FUEL REPORT

GRAPHS







GEN TECH LTD