





Machine Id **E-13** Component **Wind Turbine Gearbox** Fluid **ROYAL PURPLE SYNFILM GT 320 (65 GAL)**

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Replace filter element and resample at later date. In case already attempted and cleanliness was not improved then proceed to replace oil.

PROBLEMATIC TEST RESULTS							
Sample Status			MARGINAL	ABNORMAL	NORMAL		
Particles >6µm	ASTM D7647	>5000	<u> </u>	A 31016	3543		
Oil Cleanliness	ISO 4406 (c)	>/19/16	A 22/20/16	<u> </u>	23/19/14		

Customer Id: MITWHI Sample No.: MHI021600 Lab Number: 06016361 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

DECOMMENDE						
RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	Replace filter element and resample at later date. In case already attempted and cleanliness was not improved then proceed to replace oil.		
Resample			?	Replace filter element and resample at later date. In case already attempted and cleanliness was not improved then proceed to replace oil.		

HISTORICAL DIAGNOSIS



20 Jul 2021 Diag: Jonathan Hester

Replace filter element and resample at later date. In case already attempted and cleanliness was not improved then proceed to replace oil.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid.



view report

06 Apr 2020 Diag: Doug Bogart



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

17 Jan 2012 Diag: Doug Bogart



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The condition of oil is suitable for further service.









OIL ANALYSIS REPORT



E-13 Component Wind Turbine Gearbox Fluid ROYAL PURPLE SYNFILM GT 320 (65 GAL)

DIAGNOSIS

Machine Id

Recommendation

Replace filter element and resample at later date. In case already attempted and cleanliness was not improved then proceed to replace oil.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		MHI021600	MHI019379	MHI023867
Sample Date		Client Info		14 Apr 2023	20 Jul 2021	06 Apr 2020
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				MARGINAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184	>200	13	24	22
Iron	ppm	ASTM D5185m	>200	6	10	11
Chromium	ppm	ASTM D5185m	>3	<1	0	<1
Nickel	ppm	ASTM D5185m	>3	0	0	<1
Titanium	ppm	ASTM D5185m	>10	<1	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>30	2	0	<1
Lead	ppm	ASTM D5185m	>15	0	<1	0
Copper	ppm	ASTM D5185m	>75	5	3	5
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m	>5		0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	<1
Barium	ppm	ASTM D5185m		0	0	1
Molybdenum	ppm	ASTM D5185m		5	5	5
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m	90	<1	<1	1
Calcium	ppm	ASTM D5185m		0	0	1
Phosphorus	ppm	ASTM D5185m		0	14	8
Zinc	ppm	ASTM D5185m		0	0	4
Sulfur	ppm	ASTM D5185m		20539	14589	13821
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>+30	2	2	2
Sodium	ppm	ASTM D5185m		0	0	<1
Potassium	ppm	ASTM D5185m	>20	1	0	0
Water	%	ASTM D6304	>0.1	0.00	0.004	0.001
ppm Water	ppm	ASTM D6304	>1000	0	40.1	0.00
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		37664	108868	40374
Particles >6µm		ASTM D7647	>5000	<u> </u>	A 31016	3543
Particles >14µm		ASTM D7647	>640	394	1 705	153
Particles >21µm		ASTM D7647	>160	76	1 214	33
Particles >38µm		ASTM D7647	>40	2	9	0
Particles >71µm		ASTM D7647	>10	0	0	0
Oil Cleanliness		ISO 4406 (c)	>/19/16	<u> </u>	🔺 24/22/18	23/19/14



Particle Trend

(100) 100 mper of barticles (1 m) 100 barticles (1 m) 100 barticles (1 m) 100 barticles (1 m)

Jan 1

PQ

Abnorm

400 350 - Se 300 -250 -

문200

Water (KF)



FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.25	0.36	0.41	0.355
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	320	321	321	298
SAMPLE IMAGES		method	limit/base	current	history1	history2

Color

Bottom

pr14/23



