

PROBLEM SUMMARY

Sample Rating Trend



Machine Id 17230
Component

Diesel Engine

MOBIL DELVAC 1300 SUPER15W40 (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL			
Base Number (BN)	mg KOH/g	ASTM D2896	9.4	△ 3.4			

Customer Id: IDEBOI Sample No.: IL0033133 Lab Number: 06027083 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT



Machine Id **17230** Component

Diesel Engine

MOBIL DELVAC 1300 SUPER15W40 (--- GA





DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The BN level is low. The condition of the oil is acceptable for the time in service.

L)				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		IL0033133		
Sample Date		Client Info		24 Oct 2023		
Machine Age	mls	Client Info		345869		
Oil Age	mls	Client Info		35476		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>100	22		
Chromium	ppm	ASTM D5185m	>20	2		
Nickel	ppm	ASTM D5185m	>4	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m		4		
_ead	ppm	ASTM D5185m	>40	6		
Copper	ppm	ASTM D5185m		<1		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	12		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	0	60		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	0	546		
Calcium	ppm	ASTM D5185m		990		
Phosphorus	ppm	ASTM D5185m		539		
Zinc	ppm	ASTM D5185m		692		
Sulfur	ppm	ASTM D5185m		1820		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	7		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	12		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.7		
Nitration	Abs/cm	*ASTM D7624	>20	13.4		
Sulfation	Abs/.1mm	*ASTM D7415	>30	28.3		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	31.3		
Base Number (BN)	mg KOH/g	ASTM D2896	9.4	△ 3.4		





OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	14	13.4		

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10776874

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : IL0033133 : 06027083

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Received Diagnosed Test Package : FLEET

: 06 Dec 2023 : 08 Dec 2023 Diagnostician : Don Baldridge

RUSH TRUCK LEASING - BOISE IDEALEASE 770 WEST AMITY ROAD

BOISE, ID US 83705

Contact: MATT BORCHARDT

Contact/Location: MATT BORCHARDT - IDEBOI

borchardtm@rushenterprises.com T:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (208)639-4859