

OIL ANALYSIS REPORT






CATERPILLAR 374 10561 (S/N TNX10036)

Right Final Drive

{not provided} (--- GAL)





DIAGNOSIS

Recommendation

We suspect abnormal metal contamination may be due to sampling method. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.

High concentration of visible metal present. All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition


The condition of the oil is acceptable for the time in service.

L)				Jan 2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0879329		
Sample Date		Client Info		04 Jan 2024		
Machine Age	hrs	Client Info		918		
Oil Age	hrs	Client Info		918		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	54		
Chromium	ppm	ASTM D5185m	>10	2		
Nickel	ppm	ASTM D5185m	>5	2		
Titanium	ppm	ASTM D5185m	>15	<1		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>75	2		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>75	39		
Tin	ppm	ASTM D5185m	>8	1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		4		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		2		
Magnesium	ppm	ASTM D5185m		11		
Calcium	ppm	ASTM D5185m		3331		
Phosphorus	ppm	ASTM D5185m		1100		
Zinc	ppm	ASTM D5185m		1374		
Sulfur	ppm	ASTM D5185m		6848		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	9		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	3		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	▲ HEAVY		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		

Contact/Location: MIKE WYATT - TRANEW




OIL ANALYSIS REPORT




Color no image no image no image	FLUID PROPERTIES		method	limit/base	current	history1	history2
Color no image no image no image	Visc @ 40°C	cSt	ASTM D445		103		
	SAMPLE IMAGES		method	limit/base	current	history1	history2
Bottom no image no image no image	Color				no image	no image	no image
	Bottom				no image	no image	no image


GRAPHS



Non-ferrous Metals



Viscosity @ 40°C







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10831040

Test Package : CONST

: WC0879329 : 06059658

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved Diagnosed

: 16 Jan 2024 Diagnostician : Jonathan Hester

: 12 Jan 2024

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

TRADER CONSTRUCTION CO.

PO DRAWER 1578 NEW BERN, NC US 28563

Contact: MIKE WYATT mwyatt@traderconstruction.com

T: (252)633-1399 F: (252)638-4871