


OIL ANALYSIS REPORT

Sample Rating Trend







KANSAS/44 Machine Id 38.87 [KANSAS^44]

Transmission (Manual)

MOBIL MOBILTRANS AST 30 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The condition of the oil is acceptable for the time in service.

AST 30 (GAL)		Apr2022	Oct2022 Dec2022	Feb 2023 Jul 2023 Sep 2023	Jan2024	
SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0834090	WC0781269	WC0781238
Sample Date		Client Info		09 Jan 2024	18 Sep 2023	06 Jul 2023
Machine Age	hrs	Client Info		1890	1848	1532
Oil Age	hrs	Client Info		1890	1844	1390
Oil Changed		Client Info		Changed	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	J	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	31	25	19
Chromium	ppm	ASTM D5185m	>5	<1	0	<1
Nickel	ppm	ASTM D5185m	>5	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m	>7	0	0	0
Aluminum	ppm	ASTM D5185m	>25	2	2	1
Lead	ppm	ASTM D5185m	>45	2	2	0
Copper	ppm	ASTM D5185m	>225	19	16	13
Tin	ppm	ASTM D5185m	>10	<1	0	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	2
Barium	ppm	ASTM D5185m		0	0	2
Molybdenum	ppm	ASTM D5185m		<1	0	<1
Manganese	ppm	ASTM D5185m		<1	1	<1
Magnesium	ppm	ASTM D5185m		8	11	10
Calcium	ppm	ASTM D5185m		3177	2913	3348
Phosphorus	ppm	ASTM D5185m		1054	1042	1124
Zinc	ppm	ASTM D5185m		1262	1251	1365
Sulfur	ppm	ASTM D5185m		7714	6713	8329
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>125	12	11	11
Sodium	ppm	ASTM D5185m		0	4	4
Potassium	ppm	ASTM D5185m	>20	5	2	2
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG





OIL ANALYSIS REPORT






GRAPHS











Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10832958 Test Package : CONST

: WC0834090 : 06061576

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 16 Jan 2024 Diagnosed : 17 Jan 2024 Diagnostician : Don Baldridge

SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST WICHITA, KS

US 67213 Contact: DOUG KING doug.king@sherwood.net

T: (316)617-3161

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: