

OIL ANALYSIS REPORT

Sample Rating Trend



Jundititi



Machine Id 010924C-01

Component Fluid Fluid {not provided} (--- GAL)

DIAGNOSIS


Recommendation

This is a baseline read-out on the submitted sample.

| SAMPLE INFORM | 1ATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|----------|----------|
| Sample Number | | Client Info | | WC06062297 | | |
| Sample Date | | Client Info | | 16 Jan 2024 | | |
| Machine Age | hrs | Client Info | | 0 | | |
| Oil Age | hrs | Client Info | | 0 | | |
| Oil Changed | | Client Info | | N/A | | |
| Sample Status | | | | NORMAL | | |
| CONTAMINATION | ١ | method | limit/base | current | history1 | history2 |
| Water | | WC Method | | NEG | | |
| WEAR METALS | | method | limit/base | current | history1 | history2 |
| Iron | ppm | ASTM D5185m | | 2 | | |
| Chromium | ppm | ASTM D5185m | | 0 | | |
| Nickel | ppm | ASTM D5185m | | 0 | | |
| Titanium | ppm | ASTM D5185m | | 0 | | |
| Silver | ppm | ASTM D5185m | | 0 | | |
| Aluminum | ppm | ASTM D5185m | | 0 | | |
| Lead | ppm | ASTM D5185m | | 0 | | |
| Copper | ppm | ASTM D5185m | | 1 | | |
| Tin | ppm | ASTM D5185m | | 0 | | |
| Vanadium | ppm | ASTM D5185m | | 0 | | |
| Cadmium | ppm | ASTM D5185m | | 0 | | |
| ADDITIVES | | method | limit/base | current | history1 | history2 |
| Boron | ppm | ASTM D5185m | | 0 | | |
| Barium | ppm | ASTM D5185m | | 0 | | |
| Molybdenum | ppm | ASTM D5185m | | 0 | | |
| Manganese | ppm | ASTM D5185m | | <1 | | |
| Magnesium | ppm | ASTM D5185m | | <1 | | |
| Calcium | ppm | ASTM D5185m | | <1 | | |
| Phosphorus | ppm | ASTM D5185m | | 0 | | |
| Zinc | ppm | ASTM D5185m | | 11 | | |
| Sulfur | ppm | ASTM D5185m | | 0 | | |
| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
| Silicon | ppm | ASTM D5185m | | 0 | | |
| Sodium | ppm | ASTM D5185m | | 0 | | |
| Potassium | ppm | ASTM D5185m | >20 | 0 | | |
| SAMPLE IMAGES | ; | method | limit/base | current | history1 | history2 |
| Color | | | | no image | no image | no image |
| Bottom | | | | no image | no image | no image |



OIL ANALYSIS REPORT



MIDLAND, MI

US 48642

T:

F: