

OIL ANALYSIS REPORT

Sample Rating Trend





REXROTH HPU 4

Component

Hydraulic System

SHELL TELLUS S3 M 46 (106 GAL)

Recommendation

Resample at the next service interval to monitor.


All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




OAIVII EE IIVI OITIK	717 (1101)	method	IIIIII/Dase	Current	History	HISTOLYZ
Sample Number		Client Info		TO60001876		
Sample Date		Client Info		16 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>40	14		
Chromium	ppm	ASTM D5185m	>4	<1		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>4	2		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>60	2		
Tin	ppm	ASTM D5185m	>4	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	3	0		
Molybdenum	ppm	ASTM D5185m	0	<1		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m	0	3		
Calcium	ppm	ASTM D5185m	0	14		
Phosphorus	ppm	ASTM D5185m	106	206		
Zinc	ppm	ASTM D5185m	0	244		
Sulfur	ppm	ASTM D5185m		2135		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	4		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	2		
Water	%	ASTM D6304	>0.05	0.004		
ppm Water	ppm	ASTM D6304	>500	48		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
FLUID CLEANLIN Particles >4µm	IESS	method ASTM D7647	limit/base >5000	current 3755	history1	history2
	IESS		>5000			
Particles >4μm	IESS	ASTM D7647	>5000	3755		
Particles >4μm Particles >6μm	IESS	ASTM D7647 ASTM D7647	>5000 >1300 >160	3755 1038		
Particles >4μm Particles >6μm Particles >14μm	IESS	ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160	3755 1038 96		
Particles >4μm Particles >6μm Particles >14μm Particles >21μm	IESS	ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160 >40 >10	3755 1038 96 32		
Particles >4µm Particles >6µm Particles >14µm Particles >21µm Particles >38µm	IESS	ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160 >40 >10	3755 1038 96 32 3		
Particles >4µm Particles >6µm Particles >14µm Particles >21µm Particles >38µm Particles >71µm		ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	>5000 >1300 >160 >40 >10 >3	3755 1038 96 32 3		

Contact/Location: TONY DAVIS - MOTLAS



OIL ANALYSIS REPORT





Certificate L2367

Sample No. Lab Number **Unique Number**

: 06074684

: 10856775

Recieved Diagnosed

: 01 Feb 2024 Diagnostician : Jonathan Hester

Test Package : IND 2 (Additional Tests: KF, KV100, VI)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Las Vegas, NV US 89115

Contact: TONY DAVIS TONY.DAVIS@MOTION.COM

Contact/Location: TONY DAVIS - MOTLAS

T: F: (702)651-9466

Report Id: MOTLAS [WUSCAR] 06074684 (Generated: 02/03/2024 06:01:16) Rev: 1