

OIL ANALYSIS REPORT



ISO

Machine Id 8138342 (S/N 1013) Component

Compressor Fluid KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


istory2
istory2
story2
<mark>story2</mark>
istory2
story2
istory2
istory2
istory2
istory2
story2
story2
istory2
istory2
<mark>istory2</mark>
story2
story2
istory2 istory2




OIL ANALYSIS REPORT









US 92618 Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)